



| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------------|------------|----------------------------|--|
| 1 | GX-B1328/26-2-26062 | 2026. 5. 6 | 合格 |  |
| 2 | GX-B1322/26-2-26322~26325 | 2026/5/7 | 本次共检验电力电缆4条，4条所检项目合格。 。 |  |

| | | | | |
|---|---------------------------|----------|----------------------------|--|
| 3 | GX-B1322/26-2-26326~26327 | 2026/5/7 | 本次共检验电力电缆2条，2条所检项目合格。 。 |  |
| 4 | GX-B1322/26-2-26328~26334 | 2026/5/7 | 本次共检验电力电缆7条，7条所检项目合格。 。 |  |

| | | | | |
|---|---------------------------|----------|---------------------------------------|--|
| 5 | GX-B1322/26-2-26568~26570 | 2026/5/7 | 本次共检验电力电缆3条, 3条所检项目合格。 |  |
| 6 | GX-B1539/22-2-26014 | 2026/5/7 | 未配备司机室, 无辅助制动系统。 除上述问题外, 其余所检项目合格。 |  |

| | | | | | |
|---|---------------------|----------|---------------------------------------|--|--|
| 7 | GX-B1539/22-2-26015 | 2026/5/7 | 未配备司机室, 无辅助制动系统。 除上述问题外, 其余所检项目合格。 | |  |
| 8 | GX-B1539/22-2-26016 | 2026/5/7 | 未配备司机室, 无辅助制动系统。 除上述问题外, 其余所检项目合格。 | |  |

| | | | | | |
|----|---------------------|----------|---------------------------------------|--|--|
| 9 | GX-B1539/22-2-26017 | 2026/5/7 | 未配备司机室, 无辅助制动系统。 除上述问题外, 其余所检项目合格。 | |  <p>2026/04/27</p> |
| 10 | GX-B1539/22-2-26018 | 2026/5/7 | 未配备司机室, 无辅助制动系统。 除上述问题外, 其余所检项目合格。 | |  <p>2026/04/27</p> |

| | | | | |
|----|---------------------|----------|---------------------------------------|--|
| 11 | GX-B1539/22-2-26019 | 2026/5/7 | 未配备司机室, 无辅助制动系统。 除上述问题外, 其余所检项目合格。 |  |
| 12 | GX-B1539/22-2-26020 | 2026/5/7 | 未配备司机室, 无辅助制动系统。 除上述问题外, 其余所检项目合格。 |  |

| | | | | |
|----|---------------------|----------|---------------------------------------|--|
| 13 | GX-B1539/22-2-26021 | 2026/5/7 | 未配备司机室, 无辅助制动系统。 除上述问题外, 其余所检项目合格。 |  |
| 14 | GX-B1539/22-2-26022 | 2026/5/7 | 未配备司机室, 无辅助制动系统。 除上述问题外, 其余所检项目合格。 |  |

| | | | | | |
|----|-----------------------------|----------|------------------------------|--|--|
| 15 | GX-B1451/26-2-261004~261005 | 2026/5/6 | 本次共检高压防爆开关2台，2台高压防爆开关所检项目合格。 | |  <p>2026/04/18</p> |
| 16 | GX-B1451/26-2-261006 | 2026/5/6 | 所检项目合格。 | |  <p>2026/04/18</p> |

| | | | | |
|----|---------------------|----------|----------------------------------|--|
| 17 | GX-B1350/21-2-26034 | 2026/5/6 | 本次共检接地装置 4处，4处接地装置所 检项目合格。 |  |
| 18 | GX-B1350/21-2-26035 | 2026/5/6 | 本次共检接地装置 7处，7处接地装置所 检项目合格。 |  |

| | | | | |
|----|---------------------------|------------|----------------------------|--|
| 19 | GX-B1313/26-2-26201~26204 | 2026. 5. 7 | 所检项目合格 |  |
| 20 | GX-B1495/26-2-26074~26077 | 2026. 5. 8 | 本次共检高压开关柜4台，4台高压开关柜所检项目合格。 |  |

| | | | | |
|----|---------------------------|------------|----------------------------|--|
| 21 | GX-B1495/26-2-26078~26083 | 2026. 5. 8 | 本次共检高压开关柜6台，6台高压开关柜所检项目合格。 |  |
| 22 | GX-B1495/26-2-26084~26089 | 2026. 5. 8 | 本次共检高压开关柜6台，6台高压开关柜所检项目合格。 |  |

| | | | | |
|----|---------------------------|------------|------------------------------|--|
| 23 | GX-B1495/26-2-26090 | 2026. 5. 8 | 所检项目合格。 |  |
| 24 | GX-B1495/26-2-26091~26104 | 2026. 5. 8 | 本次共检高压开关柜14台，14台高压开关柜所检项目合格。 |  |



| | | | | |
|----|---------------------------|------------|------------------------------------|--|
| 25 | GX-B1495/26-2-26105~26109 | 2026. 5. 8 | 本次共检高压开关柜5台，5台高压开关柜所检项目合格。 |  <p>04月 23 2026.04.23 星期四 内蒙古自治区鄂尔多斯市准格尔旗 龙口镇</p> |
| 26 | GX-B1495/26-2-26003~26010 | 2026. 5. 8 | 本次共检防爆型高压配电装置8台，8台防爆型高压配电装置所检项目合格。 |  <p>地点：麻地梁煤矿中央变电所 时间：2026-04-16 星期四</p> |

| | | | | |
|----|---------------------------|------------|--------------------------------------|---|
| 27 | GX-B1495/26-2-26011~26017 | 2026. 5. 8 | 本次共检防爆型高压配电装置7台，7台防爆型高压配电装置所检项目合格。 |  <p>地点：麻地梁煤矿中央变电所 时间：2026-04-17 星期五</p> |
| 28 | GX-B1495/26-2-26018~26030 | 2026. 5. 8 | 本次共检防爆型高压配电装置13台，13台防爆型高压配电装置所检项目合格。 |  <p>地点：麻地梁煤矿采区变电所 时间：2026-04-19 星期日</p> |

| | | | | | |
|----|---------------------------|------------|---|--|---|
| 29 | GX-B1495/26-2-26031~26035 | 2026. 5. 8 | <p>本次共检防爆型高压配电装置5台，5台防爆型高压配电装置所检项目合格。</p> | |  <p>地点：麻地梁煤矿采区变电所 时间：2026-04-20 星期一</p> |
| 30 | GX-B1495/26-2-26036~26039 | 2026. 5. 8 | <p>本次共检防爆型高压配电装置4台，4台防爆型高压配电装置所检项目合格。</p> | |  <p>地点：麻地梁煤矿五煤皮带机头配电点 时间：2026-04-23 星期四</p> |

| | | | | |
|----|---------------------------|------------|---|--|
| 31 | GX-B1495/26-2-26040~26043 | 2026. 5. 8 | <p>本次共检防爆型高压配电装置4台，4台防爆型高压配电装置所检项目合格。</p> |  <p>地点：麻地梁煤矿5013胶顺机头配电点 时间：2026-04-24 星期五</p> |
| 32 | GX-B1307/26-2-26025 | 2026. 5. 8 | <p>综合判定：合格。</p> |  <p>2026/08/16</p> |

| | | | | |
|----|---------------------|------------|----------|--|
| 33 | GX-B1307/26-2-26026 | 2026. 5. 8 | 综合判定：合格。 |  |
| 34 | GX-B1307/26-2-26027 | 2026. 5. 8 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|------------|----------|--|
| 35 | GX-B1307/26-2-26028 | 2026. 5. 8 | 综合判定：合格。 |  |
| 36 | GX-B1307/26-2-26029 | 2026. 5. 8 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------------|------------|--------|--|
| 37 | GX-B1322/26-2-26472~26484 | 2026. 5. 8 | 所检项目合格 |  |
| 38 | GX-B1322/26-2-26485~26486 | 2026. 5. 8 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|------------|--------|--|
| 39 | GX-B1322/26-2-26487~26491 | 2026. 5. 8 | 所检项目合格 |  |
| 40 | GX-B1322/26-2-26492~26499 | 2026. 5. 8 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|------------|--------|--|
| 41 | GX-B1322/26-2-26523 | 2026. 5. 8 | 所检项目合格 |  |
| 42 | GX-B1322/26-2-26524~26527 | 2026. 5. 8 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|------------|--------|--|
| 43 | GX-B1322/26-2-26374~26378 | 2026. 5. 8 | 所检项目合格 |  |
| 44 | GX-B1322/26-2-26379~26381 | 2026. 5. 8 | 所检项目合格 |  |



| | | | | | | |
|----|---------------------------|------------|--------|--|--|--|
| 45 | GX-B1322/26-2-26382~26389 | 2026. 5. 8 | 所检项目合格 | |  | |
| 46 | GX-B1322/26-2-26528~26529 | 2026. 5. 8 | 所检项目合格 | |  | |

| | | | | | | |
|----|---------------------|------------|--------|--|--|--|
| 47 | GX-B1350/21-2-26036 | 2026. 5. 8 | 所检项目合格 | |  <p>2026/4/8</p> | |
| 48 | GX-B1350/21-2-26037 | 2026. 5. 8 | 所检项目合格 | |  <p>2026/04/11</p> | |

| | | | | |
|----|---------------------------|------------|--------|--|
| 49 | GX-B1451/26-2-26858~26873 | 2026. 5. 8 | 所检项目合格 |  |
| 50 | GX-B1451/26-2-26874~26881 | 2026. 5. 8 | 所检项目合格 |  |

| | | | | | |
|----|---------------------------|------------|--------|--|--|
| 51 | GX-B1451/26-2-26738~26744 | 2026. 5. 8 | 所检项目合格 | |  |
| 52 | GX-B1451/26-2-26745~26747 | 2026. 5. 8 | 所检项目合格 | |  |

| | | | | |
|----|---------------------------|------------|--------|--|
| 53 | GX-B1451/26-2-26801~26816 | 2026. 5. 8 | 所检项目合格 |  |
| 54 | GX-B1451/26-2-26817~26835 | 2026. 5. 8 | 所检项目合格 |  |


| | | | | |
|----|---------------------------|------------|--------|--|
| 55 | GX-B1451/26-2-26836~26842 | 2026. 5. 8 | 所检项目合格 |  <p>A photograph showing several workers in a control room. One worker in the foreground is kneeling and working on a yellow device on the floor. Another worker stands nearby. The room contains various control panels and equipment. A date stamp '2026/04/09' is visible in the bottom right corner of the photo.</p> |
| 56 | GX-B1451/26-2-26843~26849 | 2026. 5. 8 | 所检项目合格 |  <p>A photograph showing two workers in a control room. They are standing near a large control panel with many buttons and switches. One worker is wearing a red hard hat and a grey uniform, while the other is wearing a blue hard hat and a grey uniform. A date stamp '2026/04/10' is visible in the bottom right corner of the photo.</p> |

| | | | | |
|----|---------------------------|------------|--------|--|
| 57 | GX-B1451/26-2-26850~26857 | 2026. 5. 8 | 所检项目合格 |  |
| 58 | GX-B1313/26-2-26270~26274 | 2026. 5. 8 | 所检项目合格 |  |

| | | | | | | |
|----|---------------------------|------------|--------|--|--|--|
| 59 | GX-B1322/26-2-26335~26343 | 2026. 5. 8 | 所检项目合格 | |  | |
| 60 | GX-B1322/26-2-26344~26349 | 2026. 5. 8 | 所检项目合格 | |  | |

| | | | | | |
|----|---------------------------|------------|--------|--|--|
| 61 | GX-B1322/26-2-26350~26354 | 2026. 5. 8 | 所检项目合格 | |  |
| 62 | GX-B1322/26-2-26355~26356 | 2026. 5. 8 | 所检项目合格 | |  |



| | | | | |
|----|---------------------|------------|---------|--|
| 63 | GX-B1310/21-2-26157 | 2026. 5. 8 | 符合标准要求。 |  |
| 64 | GX-B1310/21-2-26158 | 2026. 5. 8 | 符合标准要求。 |  |


| | | | | | |
|----|---------------------|------------|---------|--|--|
| 65 | GX-B1310/21-2-26159 | 2026. 5. 8 | 符合标准要求。 | |  |
| 66 | GX-B1310/21-2-26160 | 2026. 5. 8 | 符合标准要求。 | |  |

| | | | | |
|----|---------------------|------------|---------|--|
| 67 | GX-B1310/21-2-26161 | 2026. 5. 8 | 符合标准要求。 |  <p>2026/04/09</p> |
| 68 | GX-B1310/21-2-26162 | 2026. 5. 8 | 符合标准要求。 |  <p>2026/04/10</p> |

| | | | | |
|----|---------------------|------------|----------|--|
| 69 | GX-B1428/21-2-26163 | 2026. 5. 7 | 无缺陷迹痕显示。 |  |
| 70 | GX-B1574/20-2-26003 | 2026/5/9 | 所检项目合格。 |  |

| | | | | |
|----|---------------------|----------|---------|---|
| 71 | GX-B1574/20-2-26004 | 2026/5/9 | 所检项目合格。 |  A photograph showing two workers in a tunnel. The worker on the left is wearing a light-colored uniform and a red hard hat. The worker on the right is wearing a dark blue uniform and a red hard hat, and is holding a clipboard. The background shows the interior of a tunnel with some equipment and a date stamp '2026/04/23' in the bottom right corner. |
| 72 | GX-B1574/20-2-26005 | 2026/5/9 | 所检项目合格。 |  A photograph showing two workers in a tunnel. The worker on the left is wearing a light-colored uniform and a red hard hat. The worker on the right is wearing a dark blue uniform and a red hard hat, and is holding a clipboard. The background shows the interior of a tunnel with some equipment and a date stamp '2026/04/23' in the bottom right corner. |

| | | | | |
|----|---------------------|----------|---------|--|
| 73 | GX-B1574/20-2-26006 | 2026/5/9 | 所检项目合格。 |  |
| 74 | GX-B1574/20-2-26007 | 2026/5/9 | 所检项目合格。 |  |

| | | | | |
|----|---------------------|----------|---------|---|
| 75 | GX-B1574/20-2-26008 | 2026/5/9 | 所检项目合格。 |  <p>A photograph showing two workers in a tunnel. One worker in the foreground is wearing a light-colored jacket and a red hard hat, looking towards the camera. Another worker in the background is wearing a dark jacket and a red hard hat, looking down at a piece of machinery. The date '2026/04/28' is visible in the bottom right corner of the photo.</p> |
| 76 | GX-B1574/20-2-26009 | 2026/5/9 | 所检项目合格。 |  <p>A photograph showing two workers in a tunnel. One worker in the foreground is wearing a dark jacket and a red hard hat, holding a clipboard. Another worker in the background is wearing a light-colored jacket and a red hard hat, looking towards the camera. The date '2026/04/28' is visible in the bottom right corner of the photo.</p> |

| | | | | |
|----|----------------------------|----------|------------------------------|---|
| 77 | GX-B1451/26-2-26993~261003 | 2026/5/8 | 本次共检高压开关柜11台，11台高压开关柜所检项目合格。 |  |
| 78 | GX-B1495/26-2-26044~26057 | 2026/5/9 | 本次共检高压开关柜14台，14台高压开关柜所检项目合格。 |  |



| | | | | |
|----|---------------------------|----------|------------------------------|---|
| 79 | GX-B1495/26-2-26058~26062 | 2026/5/9 | 本次共检高压开关柜5台，5台高压开关柜所检项目合格。 |  |
| 80 | GX-B1495/26-2-26063~26073 | 2026/5/9 | 本次共检高压开关柜11台，11台高压开关柜所检项目合格。 |  |

| | | | | |
|----|---------------------------|----------|----------------------------|---|
| 81 | GX-B1495/26-2-26110~26117 | 2026/5/9 | 本次共检高压开关柜8台，8台高压开关柜所检项目合格。 |  |
| 82 | GX-B1495/26-2-26118~26121 | 2026/5/9 | 本次共检高压开关柜4台，4台高压开关柜所检项目合格。 |  |

| | | | | |
|----|---------------------------|----------|-----------------------------------|---|
| 83 | GX-B1495/26-2-26122~26125 | 2026/5/9 | 本次共检继电保护装置4台，4台继电保护装置所检项目合格。 。 |  |
| 84 | GX-B1495/26-2-26126~26129 | 2026/5/9 | 本次共检继电保护装置4台，4台继电保护装置所检项目合格。 。 |  |

| | | | | |
|----|---------------------|------------|---------|---|
| 85 | GX-B1381/20-2-26001 | 2026. 5. 9 | 所检项目合格。 |  <p>2026/04/06</p> |
| 86 | GX-B1381/20-2-26002 | 2026. 5. 9 | 所检项目合格。 |  <p>2026/04/06</p> |

| | | | | |
|----|---------------------|------------|---------|---|
| 87 | GX-B1381/20-2-26003 | 2026. 5. 9 | 所检项目合格。 |  |
| 88 | GX-B1381/20-2-26004 | 2026. 5. 9 | 所检项目合格。 |  |

| | | | | |
|----|---------------------|------------|---------|---|
| 89 | GX-B1381/20-2-26005 | 2026. 5. 9 | 所检项目合格。 |  |
| 90 | GX-B1381/20-2-26006 | 2026. 5. 9 | 所检项目合格。 |  |

| | | | | |
|----|---------------------------|-------------|----------------------------|--|
| 91 | GX-B1451/26-2-26748~26750 | 2026. 5. 10 | 本次共检高压开关柜3台，3台高压开关柜所检项目合格。 |  |
| 92 | GX-B1322/26-2-26390~26391 | 2026. 5. 10 | 本次共检验电力电缆2条，2条所检项目合格。 |  |

| | | | | |
|----|---------------------------|-------------|---------------------------------|--|
| 93 | GX-B1322/26-2-26500~26507 | 2026. 5. 10 | 本次共检验电力电缆 8条，8条所检项目合 格。 |  |
| 94 | GX-B1322/26-2-26400~26419 | 2026. 5. 10 | 本次共检验电力电缆 20条，20条所检项目合 格。 |  |

| | | | | |
|----|---------------------------|-------------|----------------------------------|--|
| 95 | GX-B1322/26-2-26420~26439 | 2026. 5. 10 | 本次共检验电力电缆 20条，20条所检项目合格。 |  <p>2026/4/16</p> |
| 96 | GX-B1350/21-2-26038 | 2026. 5. 9 | 本次共检接地装置 2处，2处接地装置所 检项目合格。 |  <p>2026/04/12</p> |

| | | | | | |
|----|---------------------|------------|------------------------------------|--|--|
| 97 | GX-B1350/21-2-26039 | 2026. 5. 9 | 本次共检接地装置 3处，3处接地装置所 检项目合格。 | |  |
| 98 | GX-B1350/21-2-26040 | 2026. 5. 9 | 本次共检接地装置10 处，10处接地装置所 检项目合格。 | |  |

| | | | | |
|-----|---------------------------|------------|----------------------------|--|
| 99 | GX-B1451/26-2-26882~26883 | 2026. 5. 9 | 本次共检高压开关柜2台，2台高压开关柜所检项目合格。 |  <p>2026/04/12</p> |
| 100 | GX-B1451/26-2-26884~26891 | 2026. 5. 9 | 本次共检高压开关柜8台，8台高压开关柜所检项目合格。 |  <p>2026/04/13</p> |

| | | | | |
|-----|---------------------------|------------|------------------------------|--|
| 101 | GX-B1451/26-2-26892~26894 | 2026. 5. 9 | 本次共检高压开关柜3台，3台高压开关柜所检项目合格。 |  |
| 102 | GX-B1451/26-2-26895~26911 | 2026. 5. 9 | 本次共检高压开关柜17台，17台高压开关柜所检项目合格。 |  <p>2026/04/15</p> |

| | | | | |
|-----|---------------------|----------|---------|--|
| 103 | GX-B1611/23-2-26004 | 2026/5/8 | 所检项目合格。 |  |
| 104 | GX-B1611/23-2-26005 | 2026/5/7 | 所检项目合格。 |  |