

序号	报告编号	发布日期	结论	影像资料
1	GX-B1309/26-3-26010	2026. 5. 6	所检项目合格。	 A worker wearing a red safety helmet, a grey work jacket, and black boots is inspecting a tunnel. The worker is holding a red tool or device. The tunnel walls are rough and grey, and there are some pipes and cables visible. A timestamp '2026.04.17' is visible in the bottom right corner of the photo.
2	GX-B1500/26-3-26030	2026. 5. 6	所检项目合格。	 A worker wearing a red safety helmet, a grey work jacket, and black boots is inspecting industrial machinery. The worker is holding a red tool or device. The machinery is complex, with various pipes, valves, and a large wheel. A timestamp '2026.04.17' is visible in the bottom right corner of the photo.

3	GX-B1500/26-3-26031	2026. 5. 6	所检项目合格。	 A worker wearing a red hard hat and a grey work jacket is focused on inspecting or adjusting a large, complex industrial machine. The machine has various pipes, valves, and a blue component. The worker is standing on a yellow and black striped safety mat. A date stamp '2026.04.17' is visible in the bottom right corner of the photo.
4	GX-B1500/26-3-26032	2026. 5. 6	所检项目合格。	 A worker wearing a red hard hat and a grey work jacket is standing next to a large industrial machine. The worker is looking towards the camera. The machine has a yellow warning sign and a blue component. The worker is standing on a yellow and black striped safety mat. A date stamp '2026.04.17' is visible in the bottom right corner of the photo.

5	GX-B1312/26-3-26521	2026. 5. 6	所检项目合格	
6	GX-B1312/26-3-26522	2026. 5. 6	所检项目合格	

7	GX-B1312/26-3-26523~26524	2026. 5. 6	所检项目合格		 <p>2026.03.22</p>
8	GX-B1312/26-3-26527~26528	2026. 5. 6	所检项目合格		 <p>2026.03.24</p>

9	GX-B1312/26-3-26529~26532	2026. 5. 6	所检项目合格	 <p>2026.03.24</p>
10	GX-B1312/26-3-26533	2026. 5. 6	所检项目合格	 <p>2026.03.22</p>

11	GX-B1312/26-3-26534	2026. 5. 6	所检项目合格	
12	GX-B1312/26-3-26183~26184	2026. 5. 6	所检项目合格	

13	GX-B1312/26-3-26185	2026. 5. 6	所检项目合格	
14	GX-B1312/26-3-26189~26192	2026. 5. 6	所检项目合格	

15	GX-B1312/26-3-26193~26195	2026. 5. 6	所检项目合格		 <p>2026/3/18</p>
16	GX-B1312/26-3-26196~26199	2026. 5. 6	所检项目合格		 <p>2026/3/19</p>

17	GX-B1312/26-3-26180	2026. 5. 6	所检项目合格	
18	GX-B1312/26-3-26181~26182	2026. 5. 6	所检项目合格	

19	GX-B1312/26-3-26186	2026. 5. 6	所检项目合格	
20	GX-B1312/26-3-26187~26188	2026. 5. 6	所检项目合格	

21	GX-B1312/26-3-26200	2026. 5. 6	所检项目合格	
22	GX-B1312/26-3-26201	2026. 5. 6	所检项目合格	

23	GX-B1321/26-3-261162~261165	2026. 5. 7	所检项目合格。	 <p>2026.3.3</p>
24	GX-B1321/26-3-261166~261173	2026. 5. 7	所检项目合格。	 <p>2026.3.4</p>

25	GX-B1321/26-3-261174~261180	2026. 5. 7	所检项目合格。		 <p>2026.3.5</p>
26	GX-B1321/26-3-261181~261192	2026. 5. 7	所检项目合格。		 <p>2026.3.7</p>

27	GX-B1321/26-3-261193~261197	2026. 5. 7	所检项目合格。	 <p>2026.3.8</p>
28	GX-B1350/21-3-26020	2026. 5. 6	所检项目合格。	 <p>2026.3.25</p>



29	GX-B1350/21-3-26021	2026. 5. 6	所检项目合格。	 <p>2026.3.25</p>
30	GX-B1307/26-3-26006	2026. 5. 6	综合判定：合格。	 <p>2026.3.25</p>

31	GX-B1307/26-3-26007	2026. 5. 6	综合判定：合格。		
32	GX-B1307/26-3-26008	2026. 5. 6	综合判定：合格。		


33	GX-B1495/26-3-26681~26703	2026. 5. 7	所检项目合格	
34	GX-B1495/26-3-26704~26709	2026. 5. 7	所检项目合格	

35	GX-B1310/21-3-26223	2026. 5. 8	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	
36	GX-B1428/21-3-26027	2026. 5. 8	无缺陷痕迹显示。	

37	GX-B1310/21-3-26224	2026. 5. 8	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	
38	GX-B1428/21-3-26028	2026. 5. 8	无缺陷痕迹显示。	

39	GX-B1495/26-3-26931~26932	2026. 5. 7	所检项目合格			
40	GX-B1495/26-3-261326~261329	2026. 5. 7	所检项目合格			

41	GX-B1495/26-3-261297~261299	2026. 5. 7	所检项目合格	
42	GX-B1495/26-3-261300~261308	2026. 5. 7	所检项目合格	

43	GX-B1495/26-3-261309~261315	2026. 5. 7	所检项目合格	 A worker in a blue uniform with reflective stripes is working on a piece of electrical equipment. The worker is looking at the equipment and has their hand near it. The equipment is a large, complex machine with various components and wires. The date stamp in the bottom right corner of the photo is 2026. 3. 5.
44	GX-B1495/26-3-261316~261325	2026. 5. 7	所检项目合格	 A worker in a brown jacket and red helmet is standing in a room with electrical equipment. The worker is looking at the equipment and has their hand near their head. The room has a green floor and a blue wall. There are several pieces of electrical equipment in the room, including a large red and yellow machine. The date stamp in the bottom right corner of the photo is 2026. 3. 7.

45	GX-B1354/26-3-26001	2026. 5. 8	合格。	
46	GX-B1328/26-3-26073	2026. 5. 8	所检项目合格	



47	:GX-B1328/26-3-26074	2026. 5. 8	所检项目合格	
48	GX-B1323/26-3-26299~26302	2026. 5. 8	所检项目合格	

49	GX-B1323/26-3-26303~26305	2026. 5. 8	所检项目合格	
50	GX-B1323/26-3-26306~26308	2026. 5. 8	所检项目合格	



51	GX-B1383/26-3-26001	2026. 5. 8	所检项目合格		
52	GX-B1383/26-3-26002	2026. 5. 8	所检项目合格		

53	GX-B1323/26-3-26337~26338	2026. 5. 8	所检项目合格	
54	GX-B1323/26-3-26339~26341	2026. 5. 8	所检项目合格	

55	GX-B1323/26-3-26342~26349	2026. 5. 8	所检项目合格		
56	GX-B1329/26-3-26155~26156	2026. 5. 8	所检项目合格		

57	GX-B1329/26-3-26157~26159	2026. 5. 8	所检项目合格	
58	GX-B1329/26-3-26160~26163	2026. 5. 8	所检项目合格	

59	GX-B1329/26-3-26164~26165	2026. 5. 8	所检项目合格	
60	GX-B1329/26-3-26166~26191	2026. 5. 8	所检项目合格	


61	GX-B1328/26-3-26079	2026. 5. 11	合格	
62	GX-B1328/26-3-26080	2026. 5. 11	合格	

63	GX-B1328/26-3-26081	2026. 5. 11	合格	 <p>2026.03.23</p>
64	GX-B1328/26-3-26082	2026. 5. 11	合格	 <p>2026.03.23</p>

65	GX-B1328/26-3-26083	2026. 5. 11	合格	 <p>2026.03.23</p>
66	GX-B1404/26-3-26003	2026. 5. 7	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	 <p>2026.4.4</p>

67	GX-B1404/26-3-26004	2026. 5. 7	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。			
68	GX-B1598/24-3-26053	2026. 5. 8	实测钢丝绳有效截面积损失百分比最大为2.74%，小于5%为正常。			

69	GX-B1598/24-3-26054	2026. 5. 8	实测钢丝绳有效截面积损失百分比最大为2.94%，小于5%为正常。 。	
70	GX-B1598/24-3-26055	2026. 5. 8	实测钢丝绳有效截面积损失百分比最大为2.64%，小于5%为正常。 。	

71	GX-B1598/24-3-26056	2026. 5. 8	实测钢丝绳有效截面积损失百分比最大为2.85%，小于5%为正常。 。	
----	---------------------	------------	---------------------------------------	---