

序号	报告编号	发布日期	结论	影像资料
1	GX-B1404/20-5-26003	2026. 5. 6	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
2	GX-B1404/20-5-26004	2026. 5. 6	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

3	GX-B1404/20-5-26005	2026. 5. 6	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。		
4	GX-B1404/20-5-26006	2026. 5. 6	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。		

5	GX-B1404/20-5-26007	2026. 5. 6	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
6	GX-B1404/20-5-26008	2026. 5. 6	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

7	GX-B1404/20-5-26009	2026. 5. 6	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
8	GX-B1404/20-5-26010	2026. 5. 6	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

9	GX-B1321/26-5-26266	2026/5/6	所检项目合格。	 <p>2026年3月5日</p>
10	GX-B1303/26-5-26010	2026/5/7	综合判定：合格。	 <p>2026/04/11</p>

11	GX-B1303/26-5-26011	2026/5/7	综合判定：合格。	
12	GX-B1303/26-5-26012	2026/5/7	综合判定：合格。	

13	GX-B1305/26-5-26004	2026/5/6	综合判定：合格。	 A worker in a red safety suit and helmet is working on a large industrial machine, possibly a generator or motor, in a confined space. The machine has a large orange and silver cylindrical component. A timestamp '2020/04/24' is visible in the bottom right corner of the photo.
14	GX-B1451/26-5-26812~26818	2026/5/7	本次共检高压开关柜7台,7台高压开关柜所检项目合格。	 A worker in a red safety suit and helmet is standing in front of a control panel or electrical cabinet. The panel has various gauges, switches, and labels, including '221 2# 变压' and 'K4'. A timestamp '2020/04/07' is visible in the bottom right corner of the photo.

15	GX-B1451/26-5-26819~26840	2026/5/7	本次共检高压开关柜 22台, 22台高压开关柜 所检项目合格。	 <p>2026/04/07</p>
16	GX-B1451/26-5-26841~26855	2026/5/7	本次共检高压开关柜 15台, 15台高压开关柜 所检项目合格。	 <p>2026/04/08</p>

17	GX-B1329/26-5-26295~26297	2026/5/7	本次共检氧化锌避雷器3组，3组氧化锌避雷器所检项目合格。	
18	GX-B1329/26-5-26298	2026/5/7	所检项目合格。	

19	GX-B1451/26-5-26982~26983	2026/5/7	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	
20	GX-B1451/26-5-26984	2026/5/7	所检项目合格。	


21	GX-B1310/21-5-26186	2026/4/25	符合标准要求。	
22	GX-B1310/21-5-26187	2026/4/25	符合标准要求。	

23	GX-B1310/21-5-26188	2026/4/25	符合标准要求。	
24	GX-B1382/26-5-26011	2026. 5. 8	所检项目合格。	

25	GX-B1382/26-5-26012	2026. 5. 8	综合判定:合格。	 A photograph showing three workers in red safety suits and helmets standing in an industrial setting. They are positioned near a large piece of machinery or a structure. A date stamp '2025/4/11' is visible in the bottom right corner of the image.
26	GX-B1382/26-5-26013	2026. 5. 8	所检项目合格。	 A photograph showing three workers in red safety suits and helmets standing in an industrial setting. They are positioned near a control panel or machinery with various safety signs and symbols. A date stamp '2025/4/12' is visible in the bottom right corner of the image.

27	GX-B1382/26-5-26014	2026. 5. 8	综合判定:合格。	
28	GX-B1382/26-5-26015	2026. 5. 8	所检项目合格。	

29	GX-B1382/26-5-26016	2026. 5. 8	综合判定:合格。	
30	GX-B1382/26-5-26017	2026. 5. 8	所检项目合格。	

31	GX-B1382/26-5-26018	2026. 5. 8	综合判定:合格。	 <p>2025/4/21</p>
32	GX-B1380/26-5-26019	2026. 5. 8	所检项目合格。	 <p>2026/6/11</p>  <p>2026/4/11</p>

33	GX-B1380/26-5-26020	2026. 5. 8	所检项目合格。	
34	GX-B1380/26-5-26021	2026. 5. 8	所检项目合格。	



35	GX-B1380/26-5-26022	2026. 5. 8	所检项目合格。	
36	GX-B1328/26-5-26041	2026/5/9	本次共检绝缘手套12只，12只绝缘手套合格。	

37	GX-B1328/26-5-26042	2026/5/9	本次共检绝缘靴 12只，12只绝缘靴合格。 。	
38	GX-B1328/26-5-26043	2026/5/9	本次共检绝缘手套130 只，130只绝缘手套合 格。	

39	GX-B1328/26-5-26044	2026/5/9	本次共检绝缘靴 70只，70只绝缘靴合格。 。	 <p>2026年3月18日</p>
40	GX-B1328/26-5-26045	2026/5/9	本次共检验电器 37套，37套验电器合格。 。	 <p>2026年3月18日</p>

41	GX-B1328/26-5-26046	2026/5/9	本次共检便携式接地和接地短路装置37套，37套便携式接地和接地短路装置合格。	
42	GX-B1328/26-5-26047	2026/5/9	本次共检验电器4套，4套验电器合格。	

43	GX-B1328/26-5-26048	2026/5/9	本次共检携带式接地和接地短路装置4套，4套携带式接地和接地短路装置合格。	
44	GX-B1310/21-5-26196	2026. 5. 9	符合标准要求。	

45	GX-B1310/21-5-26197	2026. 5. 9	符合标准要求。	 <p>2026/3/30</p>
46	GX-B1310/21-5-26142	2026. 5. 9	符合标准要求。	 <p>2026/4/11</p>

47	GX-B1310/21-5-26143	2026. 5. 9	符合标准要求。	
48	GX-B1310/21-5-26144	2026. 5. 9	符合标准要求。	

49	GX-B1310/21-5-26145	2026. 5. 9	符合标准要求。	
50	GX-B1310/21-5-26146	2026. 5. 9	符合标准要求。	

51	GX-B1310/21-5-26147	2026. 5. 9	符合标准要求。	 <p>A photograph showing a worker in a red jacket and hard hat operating a yellow crane or lifting device in an industrial setting. The worker is standing on a platform, and the crane is positioned vertically. The background shows a blue sky and some structural elements of the building.</p>
52	GX-B1310/21-5-26148	2026. 5. 9	符合标准要求。	 <p>A photograph showing a worker in a white shirt and hard hat working on a large green industrial machine. The machine has a large metal ring or flange. The worker is positioned near the machine, and the background shows a concrete wall and some pipes.</p>

53	GX-B1310/21-5-26149	2026. 5. 9	符合标准要求。	 A worker in a red uniform and helmet is working on a large, dark, cylindrical industrial component. The worker is wearing a red hard hat and safety glasses. The component is mounted on a metal structure. A date stamp '2026/4/13' is visible in the bottom right corner of the image.
54	GX-B1310/21-5-26150	2026. 5. 9	符合标准要求。	 A worker in a red uniform and helmet is working on a yellow and black structure. The worker is wearing a red hard hat and safety glasses. The structure is made of metal and has yellow and black safety markings. A date stamp '2026/4/14' is visible in the bottom right corner of the image.

55	GX-B1310/21-5-26151	2026. 5. 9	符合标准要求。	 <p>A worker wearing a red hard hat and a light-colored safety vest is working on a vertical metal structure. The worker is positioned on a platform or scaffolding, and the structure appears to be part of a larger industrial or construction project. The date '2026/4/20' is visible in the bottom right corner of the image.</p>
56	GX-B1310/21-5-26152	2026. 5. 9	符合标准要求。	 <p>A worker wearing a red safety suit and a red hard hat is working on a large, orange and green industrial component. The component has a circular opening and a green section with a red handle. The worker is positioned on a platform or scaffolding, and the component appears to be part of a larger industrial or construction project. The date '2026/4/21' is visible in the bottom right corner of the image.</p>

57	GX-B1310/21-5-26153	2026. 5. 9	符合标准要求。	 A photograph showing a worker in a red safety suit and helmet working in a confined space, possibly a tunnel or underground area. The worker is positioned near large machinery, including a large wheel. The scene is dimly lit, and the worker is wearing a green tarp or covering. A yellow timestamp '2026/4/21' is visible in the bottom right corner of the image.
58	GX-B1310/21-5-26154	2026. 5. 9	符合标准要求。	 A photograph showing a worker in a red safety suit and helmet standing in a narrow metal structure, possibly a tunnel or underground area. The worker is wearing a red helmet and a red safety suit. The structure is made of metal beams and has a narrow opening. A yellow timestamp '2026/4/21' is visible in the bottom right corner of the image.

59	GX-B1427/21-5-26025	2026. 5. 7	符合标准要求。	
60	GX-B1427/21-5-26026	2026. 5. 7	符合标准要求。	

61	GX-B1427/21-5-26027	2026. 5. 7	符合标准要求。	
62	GX-B1427/21-5-26028	2026. 5. 7	符合标准要求。	

63	GX-B1427/21-5-26029	2026. 5. 7	符合标准要求。	
64	GX-B1321/26-5-26252~26265	2026. 5. 9	本次共检电力电缆14条，14条电力电缆所检项目合格。	