

序号	报告编号	发布日期	结论	影像资料
73	GX-B1309/26-5-26001	2026. 4. 28	所检项目合格。	 A photograph showing a worker in a grey uniform and red helmet inspecting a tunnel structure. The worker is standing in a narrow, dimly lit tunnel with rough rock walls. A large pipe or structure is visible in the background. A yellow timestamp '2026/2/24' is visible in the bottom right corner of the image.
74	GX-B1500/26-5-26001	2026. 4. 28	综合判定：合格。	 A photograph showing a worker in a grey uniform and red helmet inspecting a tunnel structure. The worker is standing in a narrow, dimly lit tunnel with rough rock walls. A large pipe or structure is visible in the background. A yellow timestamp '2026/2/24' is visible in the bottom right corner of the image.

75	GX-B1500/26-5-26002	2026. 4. 28	综合判定：合格。			
76	GX-B1500/26-5-26003	2026. 4. 28	综合判定：合格。			

77	GX-B1500/26-5-26004	2026. 4. 28	综合判定：合格。	
78	GX-B1309/26-5-26002	2026. 4. 28	所检项目合格。	

79	GX-B1500/26-5-26005	2026. 4. 28	综合判定：合格。		
80	GX-B1500/26-5-26006	2026. 4. 28	综合判定：合格。		


81	GX-B1500/26-5-26007	2026. 4. 28	综合判定：合格。	
82	GX-B1304/26-5-26010	2026. 4. 24	综合判定：合格。	

83	GX-B1310/21-5-26180	2026/4/20	符合标准要求。	
84	GX-B1310/21-5-26181	2026/4/20	符合标准要求。	

85	GX-B1310/21-5-26182	2026/4/20	符合标准要求。	
86	GX-B1310/21-5-26183	2026/4/20	符合标准要求。	


87	GX-B1310/21-5-26184	2026/4/20	符合标准要求。	
88	GX-B1310/21-5-26185	2026/4/20	符合标准要求。	



89	GX-B1451/26-5-26781~26788	2026/4/26	本次共检高压开关柜8台,8台高压开关柜所检项目合格。	 A photograph showing two workers in red uniforms and hard hats standing in a room with high-voltage switchgear. The workers are positioned in the center of the frame, facing the camera. The switchgear is on the left side of the image. The floor is green with yellow safety lines. A date stamp '2026/04/06' is visible in the bottom right corner of the photo.
90	GX-B1451/26-5-26789~26811	2026/4/26	本次共检高压开关柜23台,23台高压开关柜所检项目合格。	 A photograph showing a worker in a red uniform and hard hat inspecting high-voltage switchgear. The worker is standing in front of the switchgear, which is on the right side of the image. The floor is green with yellow safety lines. A date stamp '2026/04/06' is visible in the bottom right corner of the photo.

91	GX-B1329/26-5-26261~26262	2026/4/26	本次共检氧化锌避雷器2组，2组氧化锌避雷器所检项目合格。	
92	GX-B1319/26-5-26001~26003	2026/4/26	本次共检高压交流断路器3台，3台高压交流断路器所检项目合格。	

93	GX-B1319/26-5-26004~26005	2026/4/26	本次共检高压交流断路器2台，2台高压交流断路器所检项目合格。	
94	GX-B1451/26-5-26771~26773	2026/4/26	本次共检继电保护装置3台，3台继电保护装置所检项目合格。	

95	GX-B1451/26-5-26774~26776	2026/4/26	本次共检继电保护装置3台，3台继电保护装置所检项目合格。	
96	GX-B1313/26-5-26231	2026/4/26	所检项目合格。	


97	GX-B1313/26-5-26232	2026/4/26	所检项目合格。	
98	GX-B1322/26-5-26451	2026/4/26	所检项目合格。	

99	GX-B1322/26-5-26452	2026/4/26	所检项目合格。	
100	GX-B1313/26-5-26233	2026/4/26	所检项目合格。	

101	GX-B1329/26-5-26131~26174	2026年4月26日	本次共检氧化锌避雷器44组，44组氧化锌避雷器所检项目合格。	
102	GX-B1313/26-5-26270~26277	2026年4月26日	本次共检电力变压器8台，8台电力变压器所检项目合格。	

103	GX-B1313/26-5-26278~26288	2026年4月26日	本次共检电力变压器11台，11台电力变压器所检项目合格。	
104	GX-B1313/26-5-26289~26291	2026年4月26日	本次共检电力变压器3台，3台电力变压器所检项目合格。	

105	GX-B1451/26-5-26410~26425	2026年4月26日	本次共检高压开关柜16台,16台高压开关柜所检项目合格。	
106	GX-B1451/26-5-26434~26447	2026年4月26日	本次共检高压开关柜14台,14台高压开关柜所检项目合格。	

107	GX-B1451/26-5-26426~26429	2026年4月26日	本次共检高压开关柜4台4台高压开关柜所检项目合格。	
108	GX-B1451/26-5-26430~26433	2026年4月26日	本次共检高压开关柜4台,4台高压开关柜所检项目合格。	

109	GX-B1322/26-5-26460~26468	2026年4月26日	本次共检验电力电缆9条，9条所检项目合格。	
110	GX-B1350/21-5-26068	2026年4月26日	本次共检验接地装置16处，16处接地装置所检项目合格。	

111	GX-B1350/21-5-26069	2026年4月26日	本次共检验接地装置10处，10处接地装置所检项目合格。	
112	GX-B1350/21-5-26070	2026年4月26日	本次共检验接地装置6处，6处接地装置所检项目合格。	

113	GX-B1319/26-5-26020~26024	2026年4月26日	本次共检高压交流断路器5台，5台高压交流断路器所检项目合格。	
114	GX-B1313/26-5-26292	2026年4月26日	所检项目合格。	

115	GX-B1312/26-5-26139	2026/4/30	所检项目合格。	
-----	---------------------	-----------	---------	---