







序号	报告编号	发布日期	结论	影像资料
216	GX-B1500/26-2-26119	2026. 5. 12	综合判定：合格。	
217	GX-B1500/26-2-26120	2026. 5. 12	综合判定：合格。	


218	GX-B1500/26-2-26121	2026. 5. 12	综合判定：合格。		 A photograph showing a worker in a white uniform and red helmet standing next to a large green industrial machine labeled with the number '3'. The machine is situated on a raised platform with yellow safety railings. The background shows an industrial facility with various pipes and structures. A timestamp '2026/03/27' is visible in the bottom right corner of the image.
219	GX-B1500/26-2-26122	2026. 5. 12	综合判定：合格。		 A photograph showing a worker in a white uniform and red helmet standing next to a large green industrial machine labeled with the number '4'. The machine is situated on a raised platform with yellow safety railings. The background shows an industrial facility with various pipes and structures. A timestamp '2026/03/27' is visible in the bottom right corner of the image.

220	GX-B1500/26-2-26123	2026. 5. 12	综合判定：合格。	
221	GX-B1500/26-2-26131	2026. 5. 19	综合判定：合格。	

222	GX-B1500/26-2-26132	2026. 5. 19	综合判定：合格。	
223	GX-B1500/26-2-26133	2026. 5. 19	综合判定：合格。	

224	GX-B1500/26-2-26134	2026. 5. 19	综合判定：合格。	
225	GX-B1500/26-2-26135	2026. 5. 19	综合判定：合格。	

226	GX-B1500/26-2-26136	2026. 5. 19	综合判定：合格。	 A photograph showing two workers in a factory environment. They are standing next to a large green industrial machine with multiple rollers. The machine has the Chinese characters '湘电股份' (Xiangdi Company) and 'SINAMAS' on it. The workers are wearing hard hats and work clothes. A date stamp '2026/05/10' is visible in the bottom right corner of the photo.
227	GX-B1500/26-2-26137	2026. 5. 19	综合判定：合格。	 A photograph showing two workers in a factory environment, similar to the one above. They are standing next to a large green industrial machine with multiple rollers. The machine has the Chinese characters '湘电股份' (Xiangdi Company) and 'SINAMAS' on it. The workers are wearing hard hats and work clothes. A date stamp '2026/05/10' is visible in the bottom right corner of the photo.

228	GX-B1309/26-2-26029	2026. 5. 19	所检项目合格。	 <p>2026/05/10</p>
229	GX-B1313/26-2-26321~26324	2026. 5. 10	本次共检电力变压器4台，4台电力变压器所检项目合格。	 <p>2026/04/15</p>

230	GX-B1313/26-2-26325	2026. 5. 10	所检项目合格。	 A photograph showing a worker in a red uniform and helmet working on a green electrical cabinet. The worker is kneeling on the floor, and another person in a red uniform is leaning over the cabinet. There are various tools and equipment on the floor. A date stamp '2026/04/15' is visible in the bottom right corner of the image.
231	GX-B1313/26-2-26326	2026. 5. 10	所检项目合格。	 A photograph showing a worker on a utility pole at an outdoor electrical substation. The worker is wearing a red helmet and safety gear. The substation equipment is visible in the background. A date stamp '2026/04/15' is visible in the bottom right corner of the image.

232	GX-B1313/26-2-26327~26329	2026. 5. 10	本次共检电力变压器3台，3台电力变压器所检项目合格。	
233	GX-B1313/26-2-26330~26332	2026. 5. 10	本次共检电力变压器3台，3台电力变压器所检项目合格。	

234	GX-B1313/26-2-26333	2026. 5. 10	所检项目合格。	 <p>A photograph showing a worker in a grey uniform and red hard hat standing next to a large, white, cylindrical transformer in an outdoor substation. The transformer is mounted on a concrete base. Another worker is visible on top of the transformer. The date '2026/04/16' is printed in the bottom right corner of the image.</p>
235	GX-B1313/26-2-26334	2026. 5. 10	所检项目合格。	 <p>A photograph showing a worker in a grey uniform and red hard hat standing next to a transformer in an outdoor substation. The transformer is mounted on a concrete base with yellow and black diagonal safety stripes. The date '2026/04/16' is printed in the bottom right corner of the image.</p>

236	GX-B1313/26-2-26335~26338	2026. 5. 10	本次共检电力变压器4台，4台电力变压器所检项目合格。	 <p>2026/04/17</p>
237	GX-B1313/26-2-26339~26340	2026. 5. 10	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>2026/04/17</p>

238	GX-B1308/26-2-26001	2026/5/19	综合判定：合格。		 A photograph showing two workers in blue uniforms and red hard hats standing in a narrow industrial corridor. The corridor is lined with pipes and machinery. A calendar overlay in the bottom left corner shows the date 04月 10 (April 10) and 2026.04.10 星期五 (Friday, April 10, 2026).
239	GX-B1523/20-2-26001	2026/5/11	所检项目合格。		 A photograph showing two workers in dark uniforms and red hard hats standing in an underground tunnel. The tunnel is dimly lit with overhead lights. A calendar overlay in the bottom right corner shows the date 2026/04/30.

240	GX-B1322/26-2-26537	2026/5/16	所检项目合格。	 <p>2026/04/13</p>
241	GX-B1312/26-2-26032~26033	2026/5/11	本次共检干式变压器2台，2台干式变压器所检项目合格。	 <p>04月 23 2026.04.23 星期四 内蒙古自治区鄂尔多斯市准格尔旗 尔尔镇</p>

242	<u>GX-B1313/26-2-26290~26291</u>	2026. 5. 11	本次共检电力变压器2台，2台所检项目合格。 。	 <p>2026/04/12</p>
243	GX-B1380/26-2-26021	2026. 5. 20	所检项目合格	 <p>2026/05/07</p>

244	GX-B1308/26-2-26002	2026/5/21	综合判定：合格。	
245	GX-B1499/26-2-26023	2026/5/21	所检项目合格。	

246	GX-B1499/26-2-26024	2026/5/21	所检项目合格。			
247	GX-B1499/26-2-26025	2026/5/21	所检项目合格。			

248	GX-B1499/26-2-26026	2026/5/21	所检项目合格。			
-----	---------------------	-----------	---------	--	---	--