



序号	报告编号	发布日期	结论	影像资料
72	GX-B1428/21-3-26023	2026. 5. 13	无缺陷痕迹显示。	 <p>2026.03.30</p>
73	GX-B1310/21-3-26281	2026. 5. 13	符合标准要求。	 <p>2026.4.30</p>

74	GX-B1310/21-3-26229	2026. 5. 12	符合标准要求。	
75	GX-B1427/21-3-26062	2026. 5. 12	符合标准要求。	

76	GX-B1310/21-3-26230	2026. 5. 12	符合标准要求。	 A photograph showing a worker in a red jacket and red helmet working on a vertical metal structure in an industrial setting. The worker is positioned on the left side of the frame, and the structure is made of dark metal. The background shows other industrial equipment and a bright light source. A yellow timestamp '2026.4.13' is visible in the bottom right corner of the image.
77	GX-B1427/21-3-26063	2026. 5. 12	符合标准要求。	 A photograph showing a worker in a red jacket and red helmet working on a horizontal metal structure in an industrial setting. The worker is positioned on the right side of the frame, and the structure is made of dark metal. The background shows other industrial equipment and a bright light source. A yellow timestamp '2026.4.13' is visible in the bottom right corner of the image.

78	GX-B1310/21-3-26231	2026. 5. 12	符合标准要求。		 A worker wearing a red jacket, a red hard hat, and safety glasses is operating a piece of industrial machinery. The worker is standing on a platform and looking towards the camera. The machinery is dark and has some yellow markings. A yellow timestamp '2026.4.13' is visible in the bottom right corner of the photo.
79	GX-B1427/21-3-26064	2026. 5. 12	符合标准要求。		 A worker wearing a red jacket, a red hard hat, and safety glasses is standing next to industrial equipment. The worker is looking towards the camera. The equipment is dark and has some yellow markings. A yellow timestamp '2026.4.13' is visible in the bottom right corner of the photo.

80	GX-B1322/26-3-26179~26183	2026. 5. 14	所检项目合格。			
81	GX-B1321/26-3-261254~261265	2026. 5. 14	所检项目合格。			

82	GX-B1321/26-3-26657~26663	2026. 5. 14	所检项目合格。	 <p>2026. 3. 25</p>
83	GX-B1310/21-3-26261	2026. 5. 13	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 <p>2026. 04. 09</p>


84	GX-B1310/21-3-26262	2026. 5. 13	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。		 <p>2026.04.09</p>	
85	GX-B1310/21-3-26263	2026. 5. 13	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。		 <p>2026.04.14</p>	

86	GX-B1310/21-3-26264	2026. 5. 13	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 <p>2026.04.14</p>
87	GX-B1428/21-3-26029	2026. 5. 13	无缺陷痕迹显示。	 <p>2026.04.09</p>


88	GX-B1428/21-3-26030	2026. 5. 13	无缺陷迹痕显示。		 A worker wearing a red jacket and a red helmet is crouching in a dark, confined space, possibly a tunnel or a large pipe. The worker is holding a device, likely a smartphone or a tablet, and appears to be inspecting or recording data. The background shows some blue-painted metal or concrete structures. <p>2026.04.09</p>	
89	GX-B1428/21-3-26031	2026. 5. 13	无缺陷迹痕显示。		 A worker wearing a dark jacket and a red helmet is crouching in a dark, confined space, similar to the one in the first image. The worker is holding a device and appears to be inspecting or recording data. The background shows some metal or concrete structures. <p>2026.04.14</p>	



90	GX-B1428/21-3-26032	2026. 5. 13	无缺陷迹痕显示。	
91	GX-B1310/21-3-26265	2026. 5. 14	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

92	GX-B1312/26-3-26539~26540	2026. 5. 11	所检项目合格。	
93	GX-B1312/26-3-26541	2026. 5. 11	所检项目合格。	

94	GX-B1312/26-3-26542~26544	2026. 5. 11	所检项目合格。	
95	GX-B1312/26-3-26545~26546	2026. 5. 11	所检项目合格。	

96	GX-B1312/26-3-26547~26548	2026. 5. 11	所检项目合格。	
97	GX-B1312/26-3-26549~26550	2026. 5. 11	所检项目合格。	


98	GX-B1312/26-3-26551~26554	2026. 5. 11	所检项目合格。			
99	GX-B1328/26-3-26170	2026. 5. 15	合格。			

100	GX-B1328/26-3-26171	2026. 5. 15	合格。	
101	GX-B1328/26-3-26172	2026. 5. 15	合格。	

102	GX-B1309/26-3-26013	2026. 5. 15	所检项目合格。	 <p>2026.5.8</p>
103	GX-B1500/26-3-26044	2026. 5. 15	综合判定：合格。	 <p>立井水幕 井水幕 MD68-40Y</p> <p>2026.5.8</p>



104	GX-B1500/26-3-26045	2026. 5. 15	综合判定：合格。	
105	GX-B1500/26-3-26046	2026. 5. 15	综合判定：合格。	

106	GX-B1500/26-3-26047	2026. 5. 15	综合判定：合格。	
107	GX-B1309/26-3-26014	2026. 5. 15	所检项目合格。	

108	GX-B1500/26-3-26048	2026. 5. 15	综合判定：合格。	
109	GX-B1500/26-3-26049	2026. 5. 15	综合判定：合格。	

110	GX-B1500/26-3-26050	2026. 5. 15	综合判定：合格。		 A worker in a red protective suit and helmet is operating machinery in an industrial setting. The worker is positioned on the left side of the frame, facing right. The machinery is complex and appears to be part of a large-scale industrial process. The background shows a dark, possibly underground or enclosed space with some structural elements. A yellow timestamp '2026.5.8' is visible in the bottom right corner of the image.	
111	GX-B1428/21-3-26034	2026. 5. 8	无缺陷痕迹显示。		 A worker in a black jacket and red helmet is inspecting a large metal pipe. The worker is positioned on the left side of the frame, leaning over the pipe. The pipe is large and appears to be part of a complex industrial system. The background shows a structure with corrugated metal panels. A yellow timestamp '2026.3.31' is visible in the bottom right corner of the image.	

112	GX-B1309/26-3-26011	2026. 5. 15	所检项目合格。	 A worker in a red uniform and helmet is inspecting a large green pipe in a dark tunnel. The worker is holding a flashlight, and the date '2026.4.15' is visible in the bottom right corner of the photo.
113	GX-B1500/26-3-26033	2026. 5. 15	综合判定：合格。	 A worker in a red uniform and helmet is inspecting a large blue machine in a tunnel. The worker is standing next to the machine, and the date '2026.4.15' is visible in the bottom right corner of the photo.

114	GX-B1500/26-3-26034	2026. 5. 15	综合判定：合格。	
115	GX-B1500/26-3-26035	2026. 5. 15	综合判定：合格。	



116	GX-B1500/26-3-26036	2026. 5. 15	综合判定：合格。	
117	GX-B1500/26-3-26037	2026. 5. 15	所检项目合格。	

118	GX-B1309/26-3-26012	2026. 5. 15	所检项目合格。	 A worker wearing a red jacket, black pants, and a red helmet with a headlamp is inspecting a vertical metal pipe in a tunnel. The worker is holding a tool or device. The background shows the rough rock walls of the tunnel. A yellow timestamp '2026.4.18' is visible in the bottom right corner of the photo.
119	GX-B1500/26-3-26041	2026. 5. 15	综合判定：合格。	 A worker wearing a red jacket, black pants, and a red helmet with a headlamp is inspecting a large blue industrial machine in a tunnel. The worker is standing on a metal platform or staircase. The background shows the rough rock walls of the tunnel. A yellow timestamp '2026.4.18' is visible in the bottom right corner of the photo.

120	GX-B1500/26-3-26042	2026. 5. 15	综合判定：合格。	 <p>A worker wearing a red high-visibility jacket, a red hard hat, and safety boots is operating a large green industrial machine in a tunnel. The machine has a blue component on the left. The worker is standing on a wooden platform. A yellow timestamp '2026.4.18' is visible in the bottom right corner of the photo.</p>
121	GX-B1500/26-3-26043	2026. 5. 15	综合判定：合格。	 <p>A worker wearing a red high-visibility jacket, a red hard hat, and safety boots is standing next to a large industrial valve in a tunnel. The valve is white and blue. The worker is holding a metal railing. A yellow timestamp '2026.4.18' is visible in the bottom right corner of the photo.</p>

122	GX-B1308/26-3-26015	2026. 5. 19	综合判定：合格。		
123	GX-B1308/26-3-26016	2026. 5. 19	综合判定：合格。		

124	GX-B1308/26-3-26018	2026. 5. 19	综合判定：合格。			
125	GX-B1308/26-3-26019	2026. 5. 19	综合判定：合格。			

126	GX-B1308/26-3-26020	2026. 5. 19	综合判定：合格。		 <p>2026.4.10</p>	
127	GX-B1308/26-3-26021	2026. 5. 19	综合判定：合格。		 <p>2026.4.10</p>	

128	GX-B1308/26-3-26022	2026. 5. 19	综合判定：合格。		
129	GX-B1352/21-3-26081~26096	2026. 4. 2	所检项目合格。		

130	GX-B1352/21-3-26097~26125	2026. 4. 2	所检项目合格。			
131	GX-B1352/21-3-26126~26150	2026. 4. 2	所检项目合格。			

132	GX-B1359/21-3-26081~26087	2026. 4. 2	所检项目合格。		 <p>2026.1.31</p>	
133	GX-B1359/21-3-26088~26095	2026. 4. 2	所检项目合格。		 <p>2026.2.1</p>	

134	GX-B1359/21-3-26096~26103	2026. 4. 2	所检项目合格。	
135	GX-B1329/26-3-26206~26239	2026. 5. 19	所检项目合格	


136	GX-B1404/26-3-26005	2026. 5. 19	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
137	GX-B1404/26-3-26006	2026. 5. 19	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

138	GX-B1404/26-3-26007	2026. 5. 19	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
139	GX-B1404/26-3-26008	2026. 5. 19	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	



140	GX-B1404/26-3-26009	2026. 5. 19	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
141	GX-B1404/26-3-26010	2026. 5. 19	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	



142	GX-B1354/26-3-26002	2026. 5. 19	所检项目合格	
143	GX-B1354/26-3-26003	2026. 5. 20	所检项目合格	

144	GX-B1354/26-3-26004	2026. 5. 21	所检项目合格	
145	GX-B1354/26-3-26005	2026. 5. 22	所检项目合格	

146	GX-B1312/26-3-26202~26203	2026. 5. 19	所检项目合格	
147	GX-B1495/26-3-26473~26488	2026. 5. 19	所检项目合格	


148	GX-B1495/26-3-26468~26469	2026. 5. 19	所检项目合格	
149	GX-B1495/26-3-26470~26472	2026. 5. 19	所检项目合格	

150	GX-B1495/26-3-26440~26450	2026. 5. 19	所检项目合格	
151	GX-B1495/26-3-26451~26467	2026. 5. 19	所检项目合格	



152	GX-B1495/26-3-26411~26424	2026. 5. 19	所检项目合格	 <p>2026/3/15</p>
153	GX-B1495/26-3-26425~26439	2026. 5. 19	所检项目合格	 <p>2026/3/16</p>



154	GX-B1308/26-3-26017	2026. 5. 19	综合判定：合格。			
155	GX-B1308/26-3-26014	2026. 5. 19	综合判定：合格。			

156	GX-B1324/26-3-26184~26187	2026年5月20日	所检项目合格。	
157	GX-B1495/26-3-26761~26766	2026. 5. 19	所检项目合格	



158	GX-B1495/26-3-26768~26779	2026. 5. 19	所检项目合格	 <p>2026.03.14</p>
159	GX-B1495/26-3-26780~26788	2026. 5. 19	所检项目合格	 <p>2026.03.15</p>

160	GX-B1495/26-3-26791~26801	2026. 5. 19	所检项目合格			
161	GX-B1495/26-3-26802~26810	2026. 5. 19	所检项目合格			

162	GX-B1495/26-3-26811~26824	2026. 5. 19	所检项目合格			
163	GX-B1495/26-3-26825~26839	2026. 5. 19	所检项目合格			

164	GX-B1495/26-3-26841~26850	2026. 5. 19	所检项目合格		 <p>2026.03.21</p>	
165	GX-B1495/26-3-26851~26857	2026. 5. 19	所检项目合格		 <p>2026.03.22</p>	

166	GX-B1321/26-3-26400~26410	2026. 5. 20	所检项目合格	
167	GX-B1321/26-3-26411~26419	2026. 5. 20	所检项目合格	

168	GX-B1321/26-3-26420~26428	2026. 5. 20	所检项目合格		
169	GX-B1321/26-3-26429~26438	2026. 5. 20	所检项目合格		

170	GX-B1321/26-3-26439~26451	2026. 5. 20	所检项目合格	
171	GX-B1323/26-3-26179~26181	2026年5月21日	所检项目合格。	