



| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------------|------------|--|--|
| 46 | GX-B1312/26-Y-26024~26033 | 2025年5月11日 | 本次共检煤矿用防爆干式变压器10台，10台煤矿用防爆干式变压器所检项目合格。 |  <p>内蒙古神威矿业有限公司 2026/4/27</p> |
| 47 | GX-B1312/26-Y-26008~26009 | 2025年5月11日 | 本次共检煤矿用防爆干式变压器2台，2台煤矿用防爆干式变压器所检项目合格。 |  <p>乌海市大营煤矿业有限公司 2026/4/13</p> |

| | | | | | |
|----|---------------------------|------------|--------------------------------------|--|---|
| 48 | GX-B1312/26-Y-26012~26015 | 2025年5月11日 | 本次共检煤矿用防爆干式变压器4台，4台煤矿用防爆干式变压器所检项目合格。 | |  <p>马海市兴泰煤炭有限责任公司 2026/4/14</p> |
| 49 | GX-B1312/26-Y-26016~26020 | 2025年5月11日 | 本次共检煤矿用防爆干式变压器5台，5台煤矿用防爆干式变压器所检项目合格。 | |  <p>马海市兴泰煤炭有限责任公司 2026/4/16</p> |

| | | | | | |
|----|---------------------------|------------|--------------------------------------|--|---|
| 50 | GX-B1312/26-Y-26021~26022 | 2025年5月11日 | 本次共检煤矿用防爆干式变压器2台，2台煤矿用防爆干式变压器所检项目合格。 | |  <p>乌海市义善煤炭有限责任公司 2026/4/18</p> |
| 51 | GX-B1312/26-Y-26023 | 2025年5月11日 | 本次共检煤矿用防爆干式变压器1台，1台煤矿用防爆干式变压器所检项目合格。 | |  <p>乌海市义善煤炭有限责任公司 2026/4/24</p> |

| | | | | |
|----|---------------------|------------|---------|--|
| 52 | GX-B1515/26-Y-26001 | 2026年5月11日 | 所检项目合格。 |  <p>乌海市天普煤炭有限责任公司 2026年4月23日</p> |
| 53 | GX-B1515/26-Y-26002 | 2026年5月11日 | 所检项目合格。 |  <p>乌海市天普煤炭有限责任公司 2026年4月23日</p> |

| | | | | |
|----|---------------------|------------|---------|---|
| 54 | GX-B1539/26-Z-26014 | 2026年5月14日 | 所检项目合格。 |  <p>呼伦贝尔东明矿业有限责任公司 2026/5/6</p> |
| 55 | GX-B1499/26-Y-26023 | 2026年5月12日 | 所检项目合格。 |  <p>2026/4/24 乌鲁木齐市天泰煤炭有限责任公司</p> |

| | | | | |
|----|---------------------|------------|---------|--|
| 56 | GX-B1499/26-Y-26024 | 2026年5月12日 | 所检项目合格。 |  |
| 57 | GX-B1499/26-Y-26025 | 2026年5月12日 | 所检项目合格。 |  |

| | | | | |
|----|---------------------|------------|----------|--|
| 58 | GX-B1308/26-Y-26009 | 2026年5月12日 | 综合判定:合格。 |  |
| 59 | GX-B1308/26-Y-26010 | 2026年5月12日 | 所检项目合格。 |  |

| | | | | |
|----|---------------------------|------------|----------------------------------|---|
| 60 | GX-B1321/26-Y-26052~26055 | 2026年5月14日 | 本次共检电力电缆 4条，4条电力电缆所 检项目合格。 |  <p>2026/4/10 乌海市天睿煤炭有限责任公司</p> |
| 61 | GX-B1321/26-Y-26056~26063 | 2026年5月14日 | 本次共检电力电缆 8条，8条电力电缆所 检项目合格。 |  <p>2026/4/22 乌海市天睿煤炭有限责任公司</p> |

| | | | | |
|----|---------------------|------------|--------|---|
| 62 | GX-B1310/21-Y-26078 | 2026年5月12日 | 符合标准要求 |  <p>2026/4/19 马山矿业股份有限公司</p> |
| 63 | GX-B1310/21-Y-26083 | 2026年5月12日 | 符合标准要求 |  <p>2026/4/19 马山矿业股份有限公司</p> |

| | | | | |
|----|---------------------|------------|----------------------------------|--|
| 64 | GX-B1310/21-Y-26084 | 2026年5月12日 | 符合标准要求 |  <p>2026/4/23 内蒙古大唐煤炭有限责任公司</p> |
| 65 | GX-B1598/24-Y-26008 | 2026. 5. 6 | 实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。 |  <p>2026/3/7</p> |

| | | | | |
|----|---------------------|------------|---------------------------------------|--|
| 66 | GX-B1598/24-Y-26009 | 2026. 5. 6 | 实测钢丝绳有效截面积损失百分比最大为1.18%，小于5%为正常。 。 |  |
| 67 | GX-B1598/24-Y-26010 | 2026. 5. 6 | 实测钢丝绳有效截面积损失百分比最大为1.15%，小于5%为正常。 。 |  |

| | | | | |
|----|---------------------|------------|---------------------------------------|---|
| 68 | GX-B1598/24-Y-26011 | 2026. 5. 6 | 实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。 。 |  <p>2026/3/7</p> |
| 69 | GX-B1598/24-Y-26012 | 2026. 5. 6 | 实测钢丝绳有效截面积损失百分比最大为1.02%，小于5%为正常。 。 |  <p>2023/3/7</p> |

| | | | | |
|----|---------------------|------------|---------------------------------------|---|
| 70 | GX-B1598/24-Y-26013 | 2026. 5. 6 | 实测钢丝绳有效截面积损失百分比最大为1.89%，小于5%为正常。 。 |  A photograph showing a worker in a bright green raincoat and safety harness working on a structure at night. The worker is positioned on a vertical pole or beam, and the background is dark with some lights visible. A vertical timestamp '2023/5/7' is visible on the left side of the image. |
| 71 | GX-B1310/21-Y-26070 | 2026年5月19日 | 符合标准要求。 |  A photograph showing a worker in a white protective suit and red helmet working on a large industrial machine. The worker is wearing a safety harness and is focused on the task. The machine has various components and a yellow vertical bar. A red timestamp '2026年5月27日' is visible in the bottom right corner of the image. |

| | | | | |
|----|---------------------|------------|---------|---|
| 72 | GX-B1427/21-Y-26070 | 2026年5月19日 | 符合标准要求。 |  <p>2026年4月27日</p> |
| 73 | GX-B1310/21-Y-26071 | 2026年5月19日 | 符合标准要求。 |  <p>内蒙古神隆矿业有限公司 2026/4/27</p> |



| | | | | | | |
|----|---------------------|------------|---------|--|--|--|
| 74 | GX-B1310/21-Y-26072 | 2026年5月19日 | 符合标准要求。 | |  | |
| 75 | GX-B1310/21-Y-26073 | 2026年5月19日 | 符合标准要求。 | |  | |

| | | | | | |
|----|---------------------|------------|---------|--|---|
| 76 | GX-B1310/21-Y-26074 | 2026年5月19日 | 符合标准要求。 | |  <p>内蒙古神隆矿业有限公司 2026/4/27</p> |
| 77 | GX-B1310/21-Y-26075 | 2026年5月19日 | 符合标准要求。 | |  <p>内蒙古神隆矿业有限公司 2026/4/27</p> |

| | | | | |
|----|---------------------|------------|----------|---|
| 78 | GX-B1428/21-Y-26086 | 2026年5月19日 | 无缺陷迹痕显示。 |  <p>内蒙古神隆矿业公司 2026/4/28</p> |
| 79 | GX-B1310/21-Y-26087 | 2026年5月19日 | 符合标准要求。 |  <p>内蒙古神隆矿业公司 2026/4/28</p> |

| | | | | |
|----|---------------------|------------|----------|--|
| 80 | GX-B1428/21-Y-26088 | 2026年5月19日 | 无缺陷迹痕显示。 |  |
| 81 | GX-B1310/21-Y-26089 | 2026年5月19日 | 符合标准要求。 |  |

| | | | | |
|----|---------------------|------------|----------|--|
| 82 | GX-B1308/26-Y-26011 | 2026年5月18日 | 综合判定：合格。 |  |
| 83 | GX-B1499/26-Y-26026 | 2026年5月18日 | 所检项目合格。 |  |

| | | | | |
|----|---------------------|------------|---------|---|
| 84 | GX-B1499/26-Y-26027 | 2026年5月18日 | 所检项目合格。 |  <p>2026/4/18 乌海市天誉煤炭有限责任公司</p> |
| 85 | GX-B1499/26-Y-26028 | 2026年5月18日 | 所检项目合格。 |  <p>2026/4/18 乌海市天誉煤炭有限责任公司</p> |

| | | | | |
|----|---------------------|------------|---------|--|
| 86 | GX-B1499/26-Y-26029 | 2026年5月18日 | 所检项目合格。 |  |
| 87 | GX-B1499/26-Y-26030 | 2026年5月18日 | 所检项目合格。 |  |

| | | | | |
|----|---------------------|------------|---------|---|
| 88 | GX-B1308/26-Y-26013 | 2026年5月18日 | 所检项目合格。 |  <p>2026/4/18 上海浦东发展银行股份有限公司</p> |
|----|---------------------|------------|---------|---|