






序号	报告编号	发布日期	结论	影像资料
1	GX-B1341/24-9-26073	2026. 5. 7	综合判定：合格。	
2	GX-B1343/21-9-26026	2026. 5. 7	1、矿井实测风量： 7.60 m ³ /s； 2、机站静压：主通风 机556 Pa； 3、矿井通风阻力： 530.6 Pa。	

3	GX-B1371/21-9-26018	2026. 5. 7	<p>存在问题： 传感器调校记录表中 设备型号填写错误。 建议：加强传感器日 常维护及调校。 除上述问题外，其余 所检项目合格。</p>	 
4	GX-B1341/24-9-26050	2026. 5. 7	合格。	

5	GX-B1341/24-9-26051	2026. 5. 7	合格。	
6	GX-B1341/24-9-26072	2026. 5. 7	合格。	

7	GX-B1343/26-9-26019	2026. 5. 7	<p>1. 矿井实测风量： 135.32 m³/s；</p> <p>2. 机站风压：-120m水平主通风机组1400 Pa，-320m水平北中段回风井主通风机 691Pa；</p> <p>3. 矿井通风阻力：北回风井通风系统 2029.1Pa。</p>	
8	GX-B1347/26-9-26020	2026. 5. 7	<p>1. 风量(风速)合格率：100%，合格；</p> <p>2. 风源风质合格率：100%，合格；</p> <p>3. 作业场所空气质量合格率：100%，合格；</p> <p>4. 有效风量率：81.9%，合格；</p> <p>5. 风机效率：全压效率77.1%，静压效率66.0%，合格；</p> <p>6. 风量供需比：1.43，合格；</p> <p>7. 综合指标：90.3%，合格。</p>	

9	GX-B1341/24-9-26081	2026. 5. 8	综合判定：合格。	 <p>2026.04.25</p>
10	GX-B1347/26-9-26029	2026. 5. 8	<ol style="list-style-type: none"> 1. 风量（风速）合格率：100%，合格； 2. 风源风质合格率：100%，合格； 3. 作业场所空气质量合格率：100%，合格； 4. 有效风量率：86.1%，合格； 5. 风机效率：全压效率71.0%，静压效率61.3%，合格； 6. 风量供需比：1.43，合格； 7. 综合指标：89.9%，合格。 	 <p>2026.04.25</p>

11	GX-B1343/26-9-26029	2026. 5. 8	<p>1. 矿井实测风量： 84.59 m³/s；</p> <p>2. 主通风机负压：- 330m中段主通风机1260 Pa；</p> <p>3. 矿井通风阻力： 1180.3 Pa。</p>	
----	---------------------	------------	---	---