




序号	报告编号	发布日期	结论	影像资料
12	GX-B1341/24-9-26074	2026年5月12日	综合判定：合格。	 <p>2026.04.13</p>
13	GX-B1341/24-9-26075	2026年5月12日	综合判定：合格。	 <p>2026.04.13</p>

14	GX-B1343/26-9-26027	2026年5月12日	<p>1、矿井实测风量：26.62 m³/s；</p> <p>2、机站风压： I 号矿体314回风平硐主通风机689 Pa； II 号矿体325回风平硐主通风机 350 Pa；</p> <p>3、 I 号矿体314回风平硐通风系统通风阻力629.3 Pa； II 号矿体325回风平硐通风系统通风阻力272.8 Pa。</p>	
15	GX-B1594/21-9-26009	2026. 5. 12	<p>除风量、风压不判定外，其余所检项目合格。</p>	

16	GX-B1594/21-9-26010	2026. 5. 12	除风量、风压不判定外，其余所检项目合格。	 A photograph showing two workers in a dark tunnel. They are wearing red hard hats and light-colored work jackets. One worker is holding a flashlight. A red fire extinguisher is visible in the background. The date '2026.04.24' is printed in the bottom right corner of the image.
17	GX-B1594/21-9-26011	2026. 5. 12	除风量、风压不判定外，其余所检项目合格。	 A photograph showing two workers in a tunnel. They are wearing red hard hats and light-colored work jackets. They are standing near some equipment and cables. The date '2026.04.24' is printed in the bottom right corner of the image.

18	GX-B1594/21-9-26012	2026. 5. 12	风量、风压不判定，安全证件审查不合格外，其余所检项目合格。	
19	报告编号：GX-B1347/26-9-26019 代替：GX-B1343/26-9-26019	2026. 5. 12	<ol style="list-style-type: none"> 1. 风量（风速）合格率：100%，合格； 2. 风源风质合格率：100%，合格； 3. 作业场所空气质量合格率：100%，合格； 4. 有效风量率：62.11%，合格； 5. 风机效率：全压效率74.9%，静压效率73.0%，合格； 6. 风量供需比：1.32，合格； 7. 综合指标：87.6%，合格。 	 

20	GX-B1371/21-9-26010	2026. 5. 13	<p>存在问题：</p> <p>1、+14米主通风机安装的风速、一氧化碳、负压、开停传感器未接入监控系统。</p> <p>2、传感器未按照说明书进行调校。</p> <p>建议：加强传感器日常维护及调校。</p> <p>除上述问题外，其余所检项目合格。</p>	 
21	GX-B1594/21-9-26001	2026. 5. 13	<p>除风量、风压不判定外，其余所检项目合格。</p>	



22	GX-B1594/21-9-26002	2026. 5. 13	除风量、风压不判定外，其余所检项目合格。	
23	GX-B1594/21-9-26003	2026. 5. 13	除风量、风压不判定外，其余所检项目合格。	



24	GX-B1594/21-9-26004	2026. 5. 13	除风量、风压不判定外，其余所检项目合格。	
25	GX-B1594/21-9-26005	2026. 5. 13	除风量、风压不判定外，其余所检项目合格。	



26	GX-B1594/21-9-26006	2026. 5. 13	除风量、风压不判定外，其余所检项目合格。			
27	GX-B1594/21-9-26007	2026. 5. 13	除风量、风压不判定外，其余所检项目合格。			

28	GX-B1594/21-9-26008	2026. 5. 13	除风量、风压不判定外，其余所检项目合格。	 <p>2026.04.22</p>
29	GX-B1594/21-9-26013	2026. 5. 14	除风量、风压不判定外，其余所检项目合格。	 <p>2026.04.24</p>

30	GX-B1594/21-9-26014	2026. 5. 14	除风量、风压不判定外，其余所检项目合格。	 <p>2026.04.25</p>
31	GX-B1594/21-9-26015	2026. 5. 14	除风量、风压不判定外，其余所检项目合格。	 <p>2026.04.25</p>

32	GX-B1340/25-9-26011	2026. 5. 13	合格。	 <p>2026年4月14日</p>
33	GX-B1340/25-9-26012	2026. 5. 13	合格。	 <p>2026年4月14日</p>

34	GX-B1340/25-9-26005	2026. 5. 13	合格。		 <p>2026年3月22日</p>
35	GX-B1340/25-9-26006	2026. 5. 13	合格。		 <p>2026年3月22日</p>

36	GX-B1371/21-9-26021	2026. 5. 14	<p>存在问题：</p> <ol style="list-style-type: none"> 1、监测监控设备未定期进行调校； 2、无传感器调校记录表。 <p>建议：加强传感器日常维护及调校。 除上述问题外，其余所检项目合格。</p>	 
37	GX-B1371/21-9-26022	2026. 5. 14	<p>存在问题：</p> <ol style="list-style-type: none"> 1、一氧化碳传感器调校方法不正确； 2、报警记录月报表内容不全。 <p>建议：加强传感器日常维护及调校。 除上述问题外，其余所检项目合格。</p>	 

38	GX-B1371/21-9-26023	2026年5月14日	<p>存在问题：</p> <ol style="list-style-type: none"> 1、一氧化碳传感器调校方法不正确。 2、报警记录月报表内容不全。 <p>建议：加强传感器日常维护及调校。 除上述问题外，其余所检项目合格。</p>	 
39	GX-B1340/25-9-26009	2026. 5. 15	合格	

40	GX-B1340/25-9-26010	2026. 5. 15	合格	
41	GX-B1370/21-9-26005	2026. 5. 20	<p>存在问题：无安全监控设备台账。 建议：加强甲烷超限断电闭锁和故障闭锁功能维护。 除上述问题外，其余所检项目合格。</p>	 

42	GX-B1371/21-9-26017	2026.5.20	<p>存在问题： 一氧化碳传感器调校记录表中标准气样填写错误。</p> <p>建议：加强传感器日常维护及调校。</p> <p>除上述问题外，其余所检项目合格。</p>	
43	GX-B1341/24-9-26087	2026.5.20	综合判定：合格。	

44	GX-B1341/24-9-26088	2026.5.20	综合判定：合格。	 <p>2026年5月13日</p>
45	GX-B1341/24-9-26086	2026. 5. 21	综合判定：合格。	 <p>2026-05-15</p>