

序号	报告编号	发布日期	结论	影像资料
1	GX-B1312/26-1-26140~26145	2026. 6. 1	本次共检电力变压器6台，6台电力变压器所检项目合格	
2	GX-B1312/26-1-26146~26159	2026. 6. 1	本次共检电力变压器14台，14台电力变压器所检项目合格	

3	GX-B1312/26-1-26160~26167	2026. 6. 1	本次共检电力变压器8台，8台电力变压器所检项目合格	 <p>2026.4.12</p>
4	GX-B1313/26-1-26183	2026. 6. 1	所检项目合格	 <p>2026/5/15</p>

5	GX-B1303/26-1-26020	2026. 6. 1	综合判定：合格	
6	GX-B1451/26-1-26471~26493	2026. 6. 2	本次共检高压开关设备23台，23台高压开关设备所检项目合格	

7	GX-B1451/26-1-26494~26522	2026. 6. 2	本次共检高压开关设备29台，29台高压开关设备所检项目合格	
8	GX-B1451/26-1-26523~26543	2026. 6. 2	本次共检高压开关设备21台，21台高压开关设备所检项目合格	

9	GX-B1451/26-1-26544~26565	2026. 6. 2	本次共检高压开关设备22台，22台高压开关设备所检项目合格	 <p>2026.5.18</p>
10	GX-B1328/26-1-26089	2026. 6. 2	本次共检绝缘手套80只，80只绝缘手套合格	 <p>2026.5.23</p>

11	GX-B1328/26-1-26090	2026. 6. 2	本次共检绝缘靴 72只，72只绝缘靴合格	
12	GX-B1328/26-1-26102	2026. 6. 2	本次共检绝缘手套158 只，158只绝缘手套合 格	

13	GX-B1328/26-1-26103	2026. 6. 2	本次共检绝缘靴 122只，122只绝缘靴合格	 <p>内蒙古双欣矿业有限公司 2026.3.25</p>
14	GX-B1328/26-1-26104	2026. 6. 2	本次共检验电器 219支，219支验电器合格	 <p>内蒙古双欣矿业有限公司 2026.3.25</p>

15	GX-B1328/26-1-26105	2026. 6. 2	本次共检绝缘杆 12支，12支绝缘杆合格	 <p>内蒙古双欣矿业有限公司 2026.3.25</p>
16	GX-B1328/26-1-26106	2026. 6. 2	本次共检绝缘手套40 只，40只绝缘手套合 格	 <p>内蒙古双欣矿业有限公司 2026.3.24</p>



17	GX-B1328/26-1-26107	2026. 6. 2	<p>本次共检绝缘靴 40只，40只绝缘靴合格</p>	 <p>内蒙古双欣矿业有限公司 2026.3.24</p>
18	GX-B1328/26-1-26108	2026. 6. 2	<p>本次共检验电器 20支，20支验电器合格</p>	 <p>内蒙古双欣矿业有限公司 2026.3.24</p>

19	GX-B1313/26-1-26184~26192	2026. 6. 2	本次共检电力变压器9台, 9台电力变压器所检项目合格	
20	GX-B1313/26-1-26193~26202	2026. 6. 2	本次共检电力变压器10台, 10台电力变压器所检项目合格	

21	GX-B1313/26-1-26203~26204	2026. 6. 2	本次共检电力变压器2台，2台电力变压器所检项目合格	 <p>2026.5.18</p>
22	GX-B1611/23-1-26010	2026. 6. 2	所检项目合格	 <p>2026/4/21</p>

23	GX-B1380/26-1-26028	2026. 6. 3	所检项目合格	
24	GX-B1380/26-1-26029	2026. 6. 3	所检项目合格	

25	GX-B1380/26-1-26030	2026. 6. 3	所检项目合格	
26	GX-B1380/26-1-26031	2026. 6. 3	所检项目合格	

27	GX-B1380/26-1-26032	2026. 6. 3	所检项目合格	
28	GX-B1548/20-1-26001	2026. 6. 3	所检项目合格	

29	GX-B1598/24-1-26105	2026. 6. 3	实测钢丝绳有效截面积损失百分比最大为2.00%，小于5%为正常	 A photograph of a worker in a red hard hat and grey uniform standing in a tunnel. The worker is positioned next to a stack of steel beams. The background shows the interior of a tunnel with structural supports and a vehicle in the distance. A yellow timestamp '2026/4/15' is visible in the bottom right corner of the image.
30	GX-B1598/24-1-26106	2026. 6. 3	实测钢丝绳有效截面积损失百分比最大为2.35%，小于5%为正常	 A photograph of a worker in a red hard hat and grey uniform standing in a tunnel. The worker is positioned next to a stack of steel beams. The background shows the interior of a tunnel with structural supports and a vehicle in the distance. A yellow timestamp '2026/4/15' is visible in the bottom right corner of the image.

31	GX-B1598/24-1-26107	2026. 6. 3	实测钢丝绳有效截面积损失百分比最大为2.55%，小于5%为正常		
32	GX-B1598/24-1-26108	2026. 6. 3	实测钢丝绳有效截面积损失百分比最大为2.65%，小于5%为正常		

33	GX-B1598/24-1-26109	2026. 6. 3	实测钢丝绳有效截面积损失百分比最大为2.76%，小于5%为正常	 <p>2026/4/15</p>
34	GX-B1598/24-1-26110	2026. 6. 3	实测钢丝绳有效截面积损失百分比最大为3.29%，小于5%为正常	 <p>2026/4/15</p>

35	GX-B1322/26-1-26317~26323	2026. 6. 4	本次共检电力电缆 7条，7条电力电缆所 检项目合格	
36	GX-B1350/21-1-26036	2026. 6. 4	本次共检接地装置 3处，3处接地装置所 检项目合格	

37	GX-B1321/26-1-26210~26217	2026. 6. 4	本次共检电力电缆 8条，8条电力电缆所 检项目合格	
38	GX-B1321/26-1-26218~26224	2026. 6. 4	本次共检电力电缆 7条，7条电力电缆所 检项目合格	

39	GX-B1321/26-1-26225~26230	2026. 6. 4	本次共检电力电缆 6条，6条电力电缆所 检项目合格	
40	GX-B1321/26-1-26231~26233	2026. 6. 4	本次共检电力电缆 3条，3条电力电缆所 检项目合格	

41	GX-B1321/26-1-26234~26249	2026. 6. 4	本次共检电力电缆16条，16条电力电缆所检项目合格	
42	GX-B1321/26-1-26250~26268	2026. 6. 4	本次共检电力电缆19条，19条电力电缆所检项目合格	

43	GX-B1427/21-1-26202	2026. 6. 4	符合标准要求。		 <p>2026/05/15</p>
44	GX-B1310/21-1-26200	2026. 6. 4	符合标准要求。		 <p>2026/05/15</p>

45	GX-B1310/21-1-26201	2026. 6. 4	符合标准要求。	
46	GX-B1322/26-1-26324	2026. 6. 4	所检项目合格	

47	GX-B1350/21-1-26040	2026. 6. 4	所检项目合格	
48	GX-B1328/26-1-26082	2026. 6. 5	本次共检绝缘胶垫30个，30个绝缘胶垫合格	

49	GX-B1534/20-1-26001	2026. 6. 5	所检项目合格	
50	GX-B1534/20-1-26002	2026. 6. 5	所检项目合格	

51	GX-B1534/20-1-26003	2026. 6. 5	所检项目合格	
52	GX-B1534/20-1-26004	2026. 6. 5	所检项目合格	


53	GX-B1534/20-1-26005	2026. 6. 5	所检项目合格	 A photograph showing a person sitting in the driver's seat of an orange truck. The truck is parked under a structure, and the person is looking towards the camera. A red date stamp '2026.04.27' is visible in the bottom right corner of the image.
54	GX-B1534/20-1-26006	2026. 6. 5	所检项目合格	 A photograph showing a person wearing a red hard hat and a dark jacket standing next to an orange truck. The person is holding a clipboard and looking towards the camera. The truck is parked outdoors, and a red date stamp '2026.04.27' is visible in the bottom right corner of the image.

55	GX-B1534/20-1-26007	2026. 6. 5	所检项目合格	
56	GX-B1534/20-1-26008	2026. 6. 5	所检项目合格	

57	GX-B1534/20-1-26009	2026. 6. 5	所检项目合格	 A photograph showing an inspector in a grey jacket and red hard hat standing next to an orange dump truck with the number '8' on its side. The inspector is holding a clipboard and looking at it. A black bag is on the ground nearby. A red timestamp '2026.04.21' is visible in the bottom right corner of the photo.
58	GX-B1534/20-1-26010	2026. 6. 5	所检项目合格	 A photograph showing an inspector in a grey jacket and red hard hat standing in front of an orange truck with the number '12' on its front. The inspector is holding a clipboard. A red timestamp '2026.04.22' is visible in the bottom right corner of the photo.

59	GX-B1534/20-1-26011	2026. 6. 5	所检项目合格	
60	GX-B1534/20-1-26012	2026. 6. 5	所检项目合格	

61	GX-B1534/20-1-26013	2026. 6. 5	所检项目合格	
62	GX-B1534/20-1-26014	2026. 6. 5	所检项目合格	

63	GX-B1451/26-1-26566~26569	2026. 6. 5	本次共检高压开关设备4台，4台高压开关设备所检项目合格	 A photograph showing a male worker in a red hard hat, dark blue t-shirt, blue jeans, and black rubber boots. He is standing on a concrete ledge next to a large, light-colored metal high-voltage switchgear cabinet. He is wearing yellow work gloves and appears to be working on the equipment. The background shows a clear blue sky and some greenery. A red date stamp '2026.06.12' is visible in the bottom right corner of the photo.
----	---------------------------	------------	-----------------------------	---