



序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-2-26189	2026. 6. 1	符合标准要求。	 <p>2026/05/04</p>
2	GX-B1310/21-2-26190	2026. 6. 1	符合标准要求。	 <p>2026/05/04</p>

3	GX-B1310/21-2-26191	2026. 6. 1	符合标准要求。	 <p>2026/05/04</p>
4	GX-B1310/21-2-26192	2026. 6. 1	符合标准要求。	 <p>2026/05/04</p>

5	GX-B1310/21-2-26193	2026. 6. 1	符合标准要求。	
6	GX-B1310/21-2-26194	2026. 6. 1	符合标准要求。	

7	GX-B1310/21-2-26195	2026. 6. 1	符合标准要求。	 <p>2026/05/04</p>
8	GX-B1310/21-2-26196	2026. 6. 1	符合标准要求。	 <p>2026/05/04</p>

9	GX-B1310/21-2-26197	2026. 6. 1	符合标准要求。	 <p>2026/05/04</p>
10	<u>GX-B1611/23-2-26014</u>	2026. 6. 2	所检项目合格。	 <p>2026/04/17</p>



11	GX-B1611/23-2-26006	2026/6/2	所检项目合格。	
12	GX-B1611/23-2-26007	2026/6/2	所检项目合格。	

13	GX-B1308/26-2-26007	2026. 5. 30	综合判定：合格。	
14	GX-B1499-26-2-26027	2026. 6. 3	所检项目合格。	

15	GX-B1499-26-2-26028	2026. 6. 3	所检项目合格。			
16	GX-B1499-26-2-26029	2026. 6. 3	所检项目合格。			

17	GX-B1499-26-2-26030	2026. 6. 3	所检项目合格。			
18	GX-B1499-26-2-26031	2026. 6. 3	所检项目合格。			

19	GX-B1499-26-2-26032	2026. 6. 3	所检项目合格。			
20	GX-B1499-26-2-26033	2026. 6. 3	所检项目合格。			

21	GX-B1499-26-2-26034	2026. 6. 3	所检项目合格。			
22	GX-B1499-26-2-26035	2026. 6. 3	所检项目合格。			

23	GX-B1499-26-2-26036	2026. 6. 3	所检项目合格。	
24	GX-B1499-26-2-26037	2026. 6. 3	所检项目合格。	

25	GX-B1499-26-2-26038	2026. 6. 3	所检项目合格。		 A photograph of two workers in blue uniforms and red hard hats standing in a factory. They are positioned next to a large blue industrial machine. A date stamp in the bottom left corner of the photo reads "05月 06" and "2026.05.06 星期三".	
26	GX-B1499-26-2-26039	2026. 6. 3	所检项目合格。		 A photograph of two workers in blue uniforms and red hard hats standing in a factory. They are positioned next to a large blue industrial machine. A date stamp in the bottom left corner of the photo reads "05月 06" and "2026.05.06 星期三".	


27	GX-B1499-26-2-26040	2026. 6. 3	所检项目合格。		 A photograph of two workers in blue uniforms and red hard hats inspecting a large blue industrial machine in a factory. A date stamp in the bottom left corner of the photo reads "05月 06" and "2026.05.06 星期三".
28	GX-B1499-26-2-26041	2026. 6. 3	所检项目合格。		 A photograph of two workers in blue uniforms and red hard hats inspecting a large blue industrial machine in a factory. A date stamp in the bottom left corner of the photo reads "05月 06" and "2026.05.06 星期三".

29	GX-B1451/26-2-261026~261028	2026. 6. 2	本次共检高压交流断路器3台，3台高压交流断路器所检项目合格。	
30	GX-B1451/26-2-261023~261025	2026. 6. 2	本次共检高压交流断路器3台，3台高压交流断路器所检项目合格。	

31	GX-B1451/26-2-26932~26934	2026. 6. 2	本次共检继电保护装置3台，3台所检项目合格。	 <p>2026/05/11</p>
32	GX-B1451/26-2-26935~26936	2026. 6. 2	本次共检继电保护装置2台，2台所检项目合格。	 <p>2026/05/12</p>



33	GX-B1350/21-2-26047	2026. 6. 2	本次共检接地装置 2处，2处接地装置所 检项目合格。	
34	GX-B1310/21-2-26198	2026. 6. 3	符合标准要求。	

35	GX-B1310/21-2-26199	2026. 6. 3	符合标准要求。	 A worker wearing a grey uniform, a red helmet, and safety glasses is operating a piece of heavy machinery. The worker is holding a black device, possibly a camera or a sensor, and is looking towards the camera. The background shows a construction site with various metal structures and a cloudy sky. A timestamp '2026/06/14' is visible in the bottom right corner of the image.
36	GX-B1310/21-2-26200	2026. 6. 3	符合标准要求。	 A worker wearing a grey uniform, a red helmet, and safety glasses is standing on a yellow metal platform or scaffolding. The worker is holding a black device, possibly a camera or a sensor, and is looking towards the camera. The background shows a construction site with various metal structures and a cloudy sky. A timestamp '2026/06/14' is visible in the bottom right corner of the image.

37	GX-B1611/23-2-26002	2026. 6. 3	所检项目合格。	
38	GX-B1611/23-2-26003	2026. 6. 3	所检项目合格。	

39	GX-B1612/26-2-26016	2026. 6. 3	所检项目合格。	
40	GX-B1612/26-2-26017	2026. 6. 3	所检项目合格。	

41	GX-B1612/26-2-26018	2026. 6. 3	所检项目合格。	
42	GX-B1612/26-2-26019	2026. 6. 3	所检项目合格。	

43	GX-B1612/26-2-26020	2026. 6. 3	所检项目合格。	 <p>2026/04/05</p>
44	GX-B1612/26-2-26021	2026. 6. 3	所检项目合格。	 <p>2026/04/05</p>

45	GX-B1612/26-2-26022	2026. 6. 3	所检项目合格。	 <p>2026/04/05</p>
46	GX-B1612/26-2-26028	2026/6/3	除未装设后视镜外， 其余所检项目合格。 未装设后视镜。	 <p>2026/04/05</p>

47	GX-B1612/26-2-26029	2026/6/3	所检项目合格。	
48	GX-B1612/26-2-26030	2026/6/3	所检项目合格。	

49	GX-B1612/26-2-26031	2026/6/3	所检项目合格。	
50	GX-B1612/26-2-26032	2026/6/3	所检项目合格。	

51	GX-B1612/26-2-26033	2026/6/3	所检项目合格。	 <p>2026/04/06</p>
52	GX-B1612/26-2-26034	2026/6/3	所检项目合格。	 <p>2026/04/06</p>

53	GX-B1612/26-2-26035	2026/6/3	所检项目合格。	 <p>2026/04/06</p>
54	GX-B1350/21-2-26049	2026. 6. 3	本次共检接地装置 2处，2处接地装置所 检项目合格。	 <p>2026/04/13</p>

55	GX-B1322/26-2-26576~26577	2026. 6. 3	本次共检验电力电缆2条，2条所检项目合格。		 <p>2026/04/13</p>
56	GX-B1451/26-2-261029~261030	2026. 6. 3	本次共检高压开关柜2台，2台高压开关柜所检项目合格。		 <p>2026/04/13</p>

57	GX-B1329/26-2-26145~26159	2026. 6. 3	本次共检氧化锌避雷器15组，15组所检项目合格。	
58	GX-B1612/26-2-26045	2026. 6. 5	所检项目合格。	

59	GX-B1612/26-2-26046	2026. 6. 5	所检项目合格。	
60	GX-B1548/20-2-26016	2026/6/5	所检项目合格。	

61	GX-B1313/26-2-26341~26342	2026. 6. 4	所检项目合格		 <p>2026/04/13</p>
62	GX-B1598/24-2-26223	2026. 6. 4	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常。		 <p>2026/05/24</p>

63	GX-B1598/24-2-26224	2026. 6. 4	实测钢丝绳有效截面积损失百分比最大为0.98%，小于5%为正常。		
64	GX-B1598/24-2-26225	2026. 6. 4	实测钢丝绳有效截面积损失百分比最大为0.94%，小于5%为正常。		

65	GX-B1495/26-2-26149~26156	2026. 6. 3	本次共检防爆型高压 配电装置8台，8台所 检项目合格。	
66	GX-B1495/26-2-26157~26167	2026. 6. 3	本次共检防爆型高压 配电装置11台，11台所 检项目合格。	

67	GX-B1495/26-2-26136~26148	2026. 6. 3	本次共检防爆型高压 配电装置13台，13台所 检项目合格。	 <p>A photograph showing two workers in blue protective suits and red helmets inspecting high-voltage equipment. A date stamp in the bottom left corner reads '05月 12'.</p>
68	GX-B1312/26-2-26034	2026. 6. 4	所检项目合格。	 <p>A photograph showing three workers in blue protective suits and red helmets inspecting high-voltage equipment. A date stamp in the bottom left corner reads '05月 12' and '2026.05.12 星期二'.</p>

69	GX-B1312/26-2-26035~26040	2026. 6. 4	本次共检电力变压器6台，6台所检项目合格。 。	
70	GX-B1312/26-2-26041~26043	2026. 6. 4	本次共检电力变压器3台，3台所检项目合格。 。	

71	GX-B1612/26-2-26023	2026/6/4	所检项目合格。	
----	---------------------	----------	---------	---