





| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------------|------------|----------------------------------|--|
| 1 | GX-B1495/26-5-26627~26628 | 2026. 6. 3 | 本次共检高压开关设备2台，2台高压开关设备所检项目合格。 |  |
| 2 | GX-B1598/24-5- 26165 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为0.56%，小于5%为正常。 |  |



| | | | | | | |
|---|----------------------|------------|----------------------------------|--|--|--|
| 3 | GX-B1598/24-5- 26166 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为0.63%，小于5%为正常。 | |  | |
| 4 | GX-B1598/24-5- 26167 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为0.83%，小于5%为正常。 | |  | |



| | | | | | |
|---|----------------------|------------|----------------------------------|--|---|
| 5 | GX-B1598/24-5- 26168 | 2026. 6. 1 | GX-B1598/24-5- 26168 | |  A photograph showing two workers in red safety suits and helmets working on a steel cable. One worker is standing and looking at the cable, while the other is kneeling and working on it. The background shows industrial equipment and a date stamp '2026/3/7' in the bottom right corner. |
| 6 | GX-B1598/24-5- 26169 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为0.76%，小于5%为正常。 | |  A photograph showing two workers in red safety suits and helmets working on a steel cable. One worker is kneeling and working on the cable, while the other is standing and looking at it. The background shows industrial equipment and a date stamp '2026/3/7' in the bottom right corner. |

| | | | | | |
|---|----------------------|------------|----------------------------------|--|--|
| 7 | GX-B1598/24-5- 26170 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为1.09%，小于5%为正常。 | |  <p>2026/5/7</p> |
| 8 | GX-B1598/24-5- 26150 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为1.62%，小于5%为正常。 | |  <p>2026/02/14</p> |



| | | | | | | |
|----|----------------------|------------|----------------------------------|--|--|--|
| 9 | GX-B1598/24-5- 26151 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为3.89%，小于5%为正常。 | |  A photograph showing two workers in red safety suits and helmets inspecting a steel cable. The date stamp '2026/02/14' is visible in the bottom right corner. | |
| 10 | GX-B1598/24-5- 26152 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为2.93%，小于5%为正常。 | |  A photograph showing two workers in red safety suits and helmets inspecting a steel cable. The date stamp '2026/02/14' is visible in the bottom right corner. | |



| | | | | |
|----|----------------------|------------|----------------------------------|--|
| 11 | GX-B1598/24-5- 26153 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为1.43%，小于5%为正常。 |  A photograph showing two workers in red safety uniforms and helmets. They are in an industrial environment, possibly a mine or factory, and are focused on inspecting a thick steel cable. One worker is holding a tool or a part of the cable. A yellow timestamp '2026/02/14' is visible in the bottom right corner of the image. |
| 12 | GX-B1598/24-5- 26154 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为2.62%，小于5%为正常。 |  A photograph showing two workers in red safety uniforms and helmets. They are in an industrial environment, possibly a mine or factory, and are focused on inspecting a thick steel cable. One worker is holding a tool or a part of the cable. A yellow timestamp '2026/02/14' is visible in the bottom right corner of the image. |

| | | | | |
|----|----------------------|------------|----------------------------------|--|
| 13 | GX-B1598/24-5- 26155 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为2.39%，小于5%为正常。 |  |
| 14 | GX-B1598/24-5-26156 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为2.69%，小于5%为正常。 |  |

| | | | | |
|----|---------------------|------------|----------------------------------|---|
| 15 | GX-B1598/24-5-26157 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为2.71%，小于5%为正常。 |  <p>2026/2/14</p> |
| 16 | GX-B1598/24-5-26158 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为2.03%，小于5%为正常。 |  <p>2026/2/14</p> |

| | | | | |
|----|---------------------|------------|----------------------------------|--|
| 17 | GX-B1598/24-5-26159 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为1.48%，小于5%为正常。 |  |
| 18 | GX-B1598/24-5-26160 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为2.14%，小于5%为正常。 |  |

| | | | | |
|----|---------------------|------------|----------------------------------|---|
| 19 | GX-B1598/24-5-26161 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为1.98%，小于5%为正常。 |  <p>2026/2/14</p> |
| 20 | GX-B1598/24-5-26162 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为1.41%，小于5%为正常。 |  <p>2026/2/14</p> |

| | | | | |
|----|----------------------|------------|----------------------------------|--|
| 21 | GX-B1598/24-5- 26163 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为2.02%，小于5%为正常。 |  A photograph showing two workers in red safety suits and helmets working in a dark, industrial environment, likely a mine. They are positioned near a large piece of machinery or a structure, possibly related to the steel rope inspection mentioned in the text. A yellow date stamp '2026/2/14' is visible in the bottom right corner of the image. |
| 22 | GX-B1598/24-5- 26164 | 2026. 6. 1 | 实测钢丝绳有效截面积损失百分比最大为1.11%，小于5%为正常。 |  A photograph showing two workers in red safety suits and helmets working in a dark, industrial environment, likely a mine. They are positioned near a large piece of machinery or a structure, possibly related to the steel rope inspection mentioned in the text. A yellow date stamp '2026/2/14' is visible in the bottom right corner of the image. |

| | | | | |
|----|---------------------|------------|----------|--|
| 23 | GX-B1308/26-5-26027 | 2026. 6. 3 | 综合判定：合格。 |  |
| 24 | GX-B1308/26-5-26028 | 2026. 6. 3 | 综合判定：合格。 |  |

| | | | | | | |
|----|---------------------|------------|---------|--|--|--|
| 25 | GX-B1499/26-5-26072 | 2026. 6. 3 | 所检项目合格。 | |  | |
| 26 | GX-B1499/26-5-26073 | 2026. 6. 3 | 所检项目合格。 | |  | |

| | | | | |
|----|---------------------|-----------|--------------------------|--|
| 27 | GX-B1328/26-5-26158 | 2026年6月3日 | 本次共检绝缘手套 2只，2只绝缘手套合格。 |  |
| 28 | GX-B1328/26-5-26159 | 2026年6月3日 | 本次共检绝缘靴2只， 2只绝缘靴合格。 |  |

| | | | | |
|----|---------------------|------------|---------|--|
| 29 | GX-B1495/26-5-26842 | 2026. 6. 3 | 所检项目合格。 |  <p>2026/04/23</p> |
| 30 | GX-B1495/26-5-26843 | 2026. 6. 3 | 所检项目合格。 |  <p>2026/04/26</p> |

| | | | | |
|----|---------------------------|------------|--------------------------------------|--|
| 31 | GX-B1495/26-5-26809~26819 | 2026. 6. 3 | 本次共检高压开关柜 11台，11台高压开关柜 所检项目合格。 |  |
| 32 | GX-B1495/26-5-26828~26841 | 2026. 6. 3 | 本次共检高压开关柜 14台，14台高压开关柜 所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|---------------------------------|--|
| 33 | GX-B1323/21-5-25500~25501 | 2026. 6. 4 | 所检项目合格。 |  |
| 34 | GX-B1495/25-5-252500~252503 | 2026. 6. 4 | GX-B1495/25-5-252500 ~252503 |  |

| | | | | |
|----|---------------------------|------------|----------------------------------|--|
| 35 | GX-B1321/26-5-26557~26559 | 2026. 6. 4 | 本次共检电力电缆 3条，3条电力电缆所 检项目合格。 |  |
| 36 | GX-B1328/26-5-26140 | 2026年6月5日 | 本次共检绝缘手套80 只，80只绝缘手套合 格。 |  |



| | | | | |
|----|---------------------|------------|-------------------------------|--|
| 37 | GX-B1328/26-5-26141 | 2026年6月5日 | 本次共检绝缘靴 80只，80只绝缘靴合格。 。 |  |
| 38 | GX-B1310/21-5-26217 | 2026. 6. 5 | 符合标准要求。 |  |

| | | | | |
|----|---------------------------|------------|----------------------------------|--|
| 39 | GX-B1310/21-5-26218 | 2026. 6. 5 | 符合标准要求。 |  |
| 40 | GX-B1322/26-5-26600~26604 | 2026. 6. 5 | 本次共检电力电缆 5条，5条电力电缆所 检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|---------------------------------|--|
| 41 | GX-B1319/26-5-26137~26145 | 2026. 6. 5 | 本次共检高压交流断路器9台, 9台高压交流断路器所检项目合格。 |  |
| 42 | GX-B1451/26-5-261807~261815 | 2026. 6. 5 | 本次共检高压开关柜9台, 9台高压开关柜所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|-----------------------------|--|
| 43 | GX-B1451/26-5-261597~261605 | 2026. 6. 5 | 本次共检高压开关柜9台, 9台高压开关柜所检项目合格。 |  |
| 44 | GX-B1322/26-5-26605~26608 | 2026. 6. 5 | 本次共检电力电缆4条, 4条电力电缆所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|----------------------------------|--|
| 45 | GX-B1319/26-5-26146~26156 | 2026. 6. 5 | 本次共检高压交流断路器11台，11台高压交流断路器所检项目合格。 |  |
| 46 | GX-B1451/26-5-261785~261795 | 2026. 6. 5 | 本次共检高压开关柜11台，11台高压开关柜所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|-----------------------------------|--|
| 47 | GX-B1451/26-5-261606~261616 | 2026. 6. 5 | 本次共检高压开关柜11台, 11台高压开关柜所检项目合格。 |  |
| 48 | GX-B1319/26-5-26157~26167 | 2026. 6. 5 | 本次共检高压交流断路器11台, 11台高压交流断路器所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|---------------------------------------|--|
| 49 | GX-B1451/26-5-261796~261806 | 2026. 6. 5 | 本次共检高压开关柜 11台, 11台高压开关柜 所检项目合格。 |  |
| 50 | GX-B1451/26-5-261617~261627 | 2026. 6. 5 | 本次共检高压开关柜 11台, 11台高压开关柜 所检项目合格。 |  |

| | | | | | | |
|----|-----------------------------|------------|-------------------------------------|--|--|--|
| 51 | GX-B1322/26-5-26609~26611 | 2026. 6. 5 | 本次共检电力电缆 3条，3条电力电缆所 检项目合格。 | |  | |
| 52 | GX-B1451/26-5-261816~261820 | 2026. 6. 5 | 本次共检高压开关柜5 台, 5台高压开关柜所 检项目合格。 | |  | |

| | | | | | |
|----|---------------------|-----------|---------------------------|--|--|
| 53 | GX-B1350/21-5-26095 | 2026年6月5日 | 本次共检验接地装置4处，4处接地装置所检项目合格。 | |  |
| 54 | GX-B1350/21-5-26096 | 2026年6月5日 | 本次共检验接地装置2处，2处接地装置所检项目合格。 | |  |

| | | | | |
|----|-----------------------------|-----------|-----------------------------|--|
| 55 | GX-B1451/26-5-261780~261781 | 2026年6月5日 | 本次共检高压开关柜2台, 2台高压开关柜所检项目合格。 |  A worker wearing a red safety suit, a red helmet, and a headlamp is inspecting a high-voltage switch cabinet. The worker is standing in a narrow, dimly lit space. A red date stamp '2026.05.22' is visible in the bottom right corner of the photo. |
| 56 | GX-B1313/26-5-26400~26401 | 2026年6月5日 | 本次共检电力变压器2台, 2台电力变压器所检项目合格。 |  A worker wearing a black t-shirt, grey pants, and a red helmet is inspecting a power transformer. The worker is standing in front of a blue cabinet with an open door, revealing internal components. A red date stamp '2026.05.20' is visible in the bottom right corner of the photo. |

| | | | | | | |
|----|---------------------------|-----------|----------------------------|--|--|--|
| 57 | GX-B1313/26-5-26402~26407 | 2026年6月5日 | 本次共检电力变压器6台，6台电力变压器所检项目合格。 | |  | |
| 58 | GX-B1313/26-5-26408~26409 | 2026年6月5日 | 本次共检电力变压器2台，2台电力变压器所检项目合格。 | |  | |

| | | | | |
|----|---------------------------|-----------|--------------------------------|--|
| 59 | GX-B1313/26-5-26410 | 2026年6月5日 | 所检项目合格。 |  |
| 60 | GX-B1319/26-5-26130~26134 | 2026年6月5日 | 本次共检高压交流断路器5台，5台高压交流断路器所检项目合格。 |  |

| | | | | |
|----|-----------------------------|-----------|--------------------------------|--|
| 61 | GX-B1451/26-5-261590~261594 | 2026年6月5日 | 本次共检高压开关柜5台,5台高压开关柜所检项目合格。 |  |
| 62 | GX-B1319/26-5-26135~26136 | 2026年6月5日 | 本次共检高压交流断路器2台,2台高压交流断路器所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|------------------------------|--|
| 63 | GX-B1451/26-5-261595~261596 | 2026年6月5日 | 本次共检高压开关柜2台,2台高压开关柜所检项目合格。 |  |
| 64 | GX-B1451/26-5-261501~261523 | 2026. 6. 5 | 本次共检高压开关柜23台,23台高压开关柜所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|-------------------------------|--|
| 65 | GX-B1451/26-5-261524~261536 | 2026. 6. 5 | 本次共检高压开关柜13台, 13台高压开关柜所检项目合格。 |  A photograph showing a male worker wearing a red safety helmet, a red high-visibility vest over a black shirt, and dark pants. He is standing on a wooden stool, inspecting a white high-voltage switchgear cabinet. The cabinet has various control panels, switches, and warning labels. A date stamp '2026/05/19' is visible in the bottom right corner of the photo. |
| 66 | GX-B1451/26-5-261537~261539 | 2026. 6. 5 | 本次共检高压开关柜3台, 3台高压开关柜所检项目合格。 |  A photograph showing a male worker wearing a white short-sleeved shirt, white pants, and a red safety helmet. He is standing on a wooden stool, inspecting a white high-voltage switchgear cabinet. The cabinet has various control panels, switches, and warning labels. A date stamp '2026/05/20' is visible in the bottom right corner of the photo. |

| | | | | |
|----|-----------------------------|------------|---------------------------------------|--|
| 67 | GX-B1451/26-5-261540~261550 | 2026. 6. 5 | 本次共检高压开关柜 11台, 11台高压开关柜 所检项目合格。 |  |
| 68 | GX-B1451/26-5-261551~261565 | 2026. 6. 5 | 本次共检高压开关柜 15台, 15台高压开关柜 所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|---------------------------------------|--|
| 69 | GX-B1451/26-5-261566~261576 | 2026. 6. 5 | 本次共检高压开关柜 11台, 11台高压开关柜 所检项目合格。 |  <p>A worker in a red safety suit and helmet is working on a high-voltage switchgear cabinet. The worker is standing on a green safety mat with a footprint icon. The date 2026/05/22 is visible in the bottom right corner of the photo.</p> |
| 70 | GX-B1313/26-5-26370 | 2026. 6. 5 | 所检项目合格。 |  <p>A worker in a red safety vest and helmet is standing next to a high-voltage switchgear cabinet. The worker is holding a red cable. The date 2026/05/18 is visible in the bottom right corner of the photo.</p> |

| | | | | |
|----|---------------------------|------------|----------------------------|--|
| 71 | GX-B1313/26-5-26371~26372 | 2026. 6. 5 | 本次共检电力变压器2台，2台电力变压器所检项目合格。 |  A photograph of a male worker wearing a red hard hat, safety glasses, and a high-visibility safety vest over a grey shirt. He is standing in a narrow aisle between tall, grey metal electrical cabinets. On the floor in front of him is a black toolbox containing various colored cables and tools. A yellow timestamp '2026/05/19' is visible in the bottom right corner of the photo. |
| 72 | GX-B1313/26-5-26373~26377 | 2026. 6. 5 | 本次共检电力变压器5台，5台电力变压器所检项目合格。 |  A photograph of the same worker from the first photo, wearing a red hard hat and safety glasses. He is standing in a room with various electrical equipment, including a large red transformer or component. A black toolbox with cables is on the floor near his feet. A yellow timestamp '2026/05/20' is visible in the bottom right corner of the photo. |

| | | | | |
|----|---------------------------|------------|----------------------------|--|
| 73 | GX-B1313/26-5-26378~26384 | 2026. 6. 5 | 本次共检电力变压器7台，7台电力变压器所检项目合格。 |  |
| 74 | GX-B1313/26-5-26385~26386 | 2026. 6. 5 | 本次共检电力变压器2台，2台电力变压器所检项目合格。 |  |

| | | | | |
|----|---------------------------|------------|----------------------------|--|
| 75 | GX-B1313/26-5-26387~26389 | 2026. 6. 5 | 本次共检电力变压器3台，3台电力变压器所检项目合格。 |  |
| 76 | GX-B1322/26-5-26580~26588 | 2026. 6. 4 | 本次共检电力电缆9条，9条电力电缆所检项目合格。 |  |

| | | | | |
|----|---------------------------|------------|----------------------------------|--|
| 77 | GX-B1322/26-5-26589~26593 | 2026. 6. 4 | 本次共检电力电缆 5条，5条电力电缆所 检项目合格。 |  A worker wearing a red safety vest and a red helmet is kneeling on a green floor, operating a piece of electronic equipment. The equipment has various cables connected to it. A timestamp '2026/05/19' is visible in the bottom right corner of the photo. |
| 78 | GX-B1322/26-5-26594~26595 | 2026. 6. 4 | 本次共检电力电缆 2条，2条电力电缆所 检项目合格。 |  A worker wearing a red safety vest and a red helmet is kneeling on a green floor, operating a piece of electronic equipment. The equipment has various cables connected to it. A timestamp '2026/05/21' is visible in the bottom right corner of the photo. |

| | | | | |
|----|---------------------------|------------|----------------------------------|--|
| 79 | GX-B1322/26-5-26596 | 2026. 6. 4 | 所检项目合格。 |  |
| 80 | GX-B1319/26-5-26040~26062 | 2026. 6. 5 | 本次共检高压交流断路器23台，23台高压交流断路器所检项目合格。 |  |

| | | | | |
|----|---------------------------|------------|----------------------------------|--|
| 81 | GX-B1319/26-5-26063~26077 | 2026. 6. 5 | 本次共检高压交流断路器15台，15台高压交流断路器所检项目合格。 |  A worker wearing a red hard hat and a high-visibility safety vest is working on a high-voltage switchgear cabinet. The worker is holding a tool and appears to be inspecting or adjusting a component inside the cabinet. The cabinet is white with various panels and components. A date stamp '2026/05/19' is visible in the bottom right corner of the image. |
| 82 | GX-B1319/26-5-26078~26080 | 2026. 6. 5 | 本次共检高压交流断路器3台，3台高压交流断路器所检项目合格。 |  A worker wearing a red hard hat and a grey work jacket is working on a high-voltage switchgear cabinet. The worker is holding a tool and appears to be inspecting or adjusting a component inside the cabinet. The cabinet is white with various panels and components. A date stamp '2026/05/20' is visible in the bottom right corner of the image. |

| | | | | |
|----|---------------------------|------------|----------------------------------|--|
| 83 | GX-B1319/26-5-26081~26091 | 2026. 6. 5 | 本次共检高压交流断路器11台，11台高压交流断路器所检项目合格。 |  |
| 84 | GX-B1319/26-5-26092~26106 | 2026. 6. 5 | 本次共检高压交流断路器15台，15台高压交流断路器所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|----------------------------------|--|
| 85 | GX-B1319/26-5-26107~26117 | 2026. 6. 5 | 本次共检高压交流断路器11台，11台高压交流断路器所检项目合格。 |  |
| 86 | GX-B1451/26-5-261701~261723 | 2026. 6. 5 | 本次共检高压开关柜23台，23台高压开关柜所检项目合格。 |  |

| | | | | |
|----|-----------------------------|------------|---------------------------------------|---|
| 87 | GX-B1451/26-5-261724~261736 | 2026. 6. 5 | 本次共检高压开关柜 13台, 13台高压开关柜 所检项目合格。 |  A worker wearing a red hard hat and a high-visibility safety vest is kneeling on a green mat inside a high-voltage switchgear cabinet. The worker is focused on a task, possibly inspecting or working on the internal components. The cabinet has yellow warning signs on the door. A timestamp '2026/05/19' is visible in the bottom right corner of the photo. |
| 88 | GX-B1451/26-5-261737~261747 | 2026. 6. 5 | 本次共检高压开关柜 11台, 11台高压开关柜 所检项目合格。 |  A worker wearing a red hard hat and a light-colored safety vest is kneeling on a dark mat inside a high-voltage switchgear cabinet. The worker is looking towards the camera while working on the internal components. The cabinet has a blue wall in the background. A timestamp '2026/05/20' is visible in the bottom right corner of the photo. |

| | | | | | |
|----|-----------------------------|------------|---------------------------------------|--|--|
| 89 | GX-B1451/26-5-261748~261762 | 2026. 6. 5 | 本次共检高压开关柜 15台, 15台高压开关柜 所检项目合格。 | |  |
| 90 | GX-B1451/26-5-261763~261773 | 2026. 6. 5 | 本次共检高压开关柜 11台, 11台高压开关柜 所检项目合格。 | |  |

| | | | | | |
|----|---------------------|------------|---------------------------|--|--|
| 91 | GX-B1350/21-5-26090 | 2026. 6. 4 | 本次共检验接地装置5处，5处接地装置所检项目合格。 | |  <p>2026/05/21</p> |
| 92 | GX-B1350/21-5-26091 | 2026. 6. 4 | 本次共检验接地装置2处，2处接地装置所检项目合格。 | |  <p>2026/05/22</p> |

| | | | | |
|----|---------------------|------------|---------|---|
| 93 | GX-B1312/26-5-26150 | 2026. 6. 5 | 所检项目合格。 |  <p>2026.3.10</p> |
| 94 | GX-B1310/21-5-26204 | 2026. 6. 5 | 符合标准要求。 |  <p>2026.5.10</p> |

| | | | | |
|----|---------------------|----------|----------|--|
| 95 | GX-B1416/22-5-26005 | 2026/6/5 | 综合判定:合格。 |  |
| 96 | GX-B1416/22-5-26006 | 2026/6/5 | 综合判定:合格。 |  |

| | | | | |
|----|---------------------|----------|----------|--|
| 97 | GX-B1416/22-5-26007 | 2026/6/5 | 综合判定:合格。 |  |
| 98 | GX-B1416/22-5-26008 | 2026/6/5 | 综合判定:合格。 |  |

| | | | | |
|-----|---------------------|----------|----------|--|
| 99 | GX-B1416/22-5-26009 | 2026/6/5 | 综合判定:合格。 |  |
| 100 | GX-B1416/22-5-26010 | 2026/6/5 | 综合判定:合格。 |  |

| | | | | |
|-----|---------------------|----------|----------|--|
| 101 | GX-B1416/22-5-26011 | 2026/6/5 | 综合判定:合格。 |  |
| 102 | GX-B1416/22-5-26012 | 2026/6/5 | 综合判定:合格。 |  |