

序号	报告编号	发布日期	结论	影像资料
1	GX-B1539/26-Y-26015	2026年6月1日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface under a clear blue sky. Two workers wearing red hard hats and work clothes are standing next to the loader. A yellow date stamp '2026/5/17' is visible in the bottom right corner of the photo.
2	GX-B1539/26-Y-26016	2026年6月1日	所检项目合格。	 A close-up view of the cab of a yellow wheel loader. The cab is yellow and has a large window. A green circular sticker is visible on the front of the cab. A yellow date stamp '2026/5/17' is visible in the bottom right corner of the photo.

3	GX-B1539/26-Y-26017	2026年6月1日	所检项目合格。	
4	GX-B1539/26-Y-26018	2026年6月1日	所检项目合格。	

5	GX-B1539/26-Y-26019	2026年6月1日	所检项目合格。	
6	GX-B1539/26-Y-26020	2026年6月1日	所检项目合格。	

7	GX-B1539/26-Y-26021	2026年6月1日	所检项目合格。	
8	GX-B1539/26-Y-26022	2026年6月2日	所检项目合格。	

9	GX-B1539/26-Y-26023	2026年6月2日	所检项目合格。	
10	GX-B1539/26-Y-26024	2026年6月2日	所检项目合格。	

11	GX-B1539/26-Y-26025	2026年6月2日	所检项目合格。	
12	GX-B1539/26-Y-26026	2026年6月2日	所检项目合格。	

13	GX-B1539/26-Y-26027	2026年6月2日	所检项目合格。	
14	GX-B1539/26-Y-26028	2026年6月2日	所检项目合格。	

15	GX-B1539/26-Y-26029	2026年6月2日	所检项目合格。	
16	GX-B1308/26-Y-26014	2026. 6. 4	所检项目合格。	

17	GX-B1310/21-Y-26076	2026年6月5日	符合标准要求。	 <p>贵州和隆矿业股份有限公司 2026/4/23</p>
18	GX-B1310/21-Y-26077	2026年6月5日	符合标准要求。	 <p>贵州和隆矿业股份有限公司 2026/4/23</p>

19	GX-B1515/26-Y-26004	2026年6月5日	所检项目合格。		 <p>乌海市天誉煤炭有限责任公司 2026年4月24日</p>	
20	GX-B1515/26-Y-26005	2026年6月5日	所检项目合格。		 <p>乌海市天誉煤炭有限责任公司 2026年4月24日</p>	