







序号	报告编号	发布日期	结论	影像资料
1	GX-B1361/26-A-26380	2026/6/1	所检项目合格	
2	GX-B1361/26-A-26381	2026/6/1	所检项目合格	



3	GX-B1361/26-A-26389	2026/6/1	合格	
4	GX-B1361/26-A-26390	2026/6/1	合格	

5	GX-B1361/26-A-26338	2026/6/2	所检项目合格	
6	GX-B1361/26-A-26339	2026/6/2	所检项目合格	

7	GX-B1361/26-A-26364	2026/6/2	所检项目合格	
8	GX-B1361/26-A-26365	2026/6/2	所检项目合格	

9	GX-B1361/26-A-26366	2026/6/2	所检项目合格	
10	GX-B1361/26-A-26367	2026/6/2	所检项目合格	

11	GX-B1361/26-A-26368	2026/6/2	所检项目合格	
12	GX-B1361/26-A-26369	2026/6/2	所检项目合格	


13	GX-B1361/26-A-26370	2026/6/2	所检项目合格	
14	GX-B1361/26-A-26371	2026/6/2	所检项目合格	

15	GX-B1361/26-A-26372	2026/6/2	所检项目合格	
16	GX-B1361/26-A-26373	2026/6/2	所检项目合格	

17	GX-B1361/26-A-26374	2026/6/2	所检项目合格	
18	GX-B1361/26-A-26375	2026/6/2	所检项目合格	



19	GX-B1361/26-A-26376	2026/6/2	所检项目合格	 A photograph showing two technicians in light blue uniforms working with a piece of industrial equipment. One technician is seated and facing the machine, while the other stands to the right, looking at the machine. The machine has a blue label with the Chinese characters '校准仪器' (Calibration Instrument) and a yellow warning sign. A date stamp '2026/5/27' is visible in the bottom right corner of the photo.
20	GX-B1361/26-A-26377	2026/6/2	所检项目合格	 A photograph showing two technicians in light blue uniforms working with a piece of industrial equipment. One technician is seated and facing the machine, while the other stands to the right, looking at the machine. The machine has a blue label with the Chinese characters '校准仪器' (Calibration Instrument) and a yellow warning sign. A date stamp '2026/5/27' is visible in the bottom right corner of the photo.


21	GX-B1361/26-A-26378	2026/6/2	所检项目合格	
22	GX-B1361/26-A-26379	2026/6/2	所检项目合格	



23	GX-B1362/23-A-26491	2026/6/2	所检项目合格	
24	GX-B1362/23-A-26492	2026/6/2	所检项目合格	



25	GX-B1362/23-A-26493	2026/6/2	所检项目合格	
26	GX-B1362/23-A-26499	2026/6/2	合格	



27	GX-B1362/23-A-26500	2026/6/2	合格	
28	GX-B1362/23-A-26501	2026/6/2	合格	

29	GX-B1362/23-A-26502	2026/6/2	合格	
30	GX-B1362/23-A-26503	2026/6/2	合格	



31	GX-B1362/23-A-26504	2026/6/2	合格	
32	GX-B1362/23-A-26505	2026/6/2	合格	



33	GX-B1362/23-A-26506	2026/6/2	合格	
34	GX-B1362/23-A-26507	2026/6/2	合格	



35	GX-B1362/23-A-26508	2026/6/2	合格	
36	GX-B1362/23-A-26509	2026/6/2	合格	



37	GX-B1362/23-A-26522	2026/6/3	不合格	
38	GX-B1362/23-A-26523	2026/6/3	不合格	

39	GX-B1362/23-A-26535	2026/6/4	所检项目结果见报告内页	
40	GX-B1362/23-A-26536	2026/6/4	所检项目结果见报告内页	

41	GX-B1361/26-A-26423	2026/6/4	所检项目合格	
42	GX-B1361/26-A-26313	2026/6/5	最小钢丝破断拉力总和结果2130.18，其余所检项目合格。	



43	GX-B1361/26-A-26382	2026/6/5	所检项目合格	
44	GX-B1361/26-A-26383	2026/6/5	所检项目合格	

45	GX-B1361/26-A-26384	2026/6/5	所检项目合格	 A technician in a light blue uniform is working on a large industrial machine. Another technician is visible in the background. A yellow date stamp '2026/5/29' is in the bottom right corner.
46	GX-B1361/26-A-26385	2026/6/5	合格	 Two technicians in light blue uniforms are working at a control panel. One technician is wearing a uniform with the '中检公信' logo. A yellow date stamp '2026/5/29' is in the bottom right corner.

47	GX-B1361/26-A-26386	2026/6/5	合格	
48	GX-B1361/26-A-26387	2026/6/5	合格	



49	GX-B1361/26-A-26388	2026/6/5	合格	
50	GX-B1361/26-A-26391	2026/6/5	所检项目合格	



51	GX-B1361/26-A-26392	2026/6/5	所检项目合格	
52	GX-B1361/26-A-26393	2026/6/5	所检项目合格	



53	GX-B1361/26-A-26394	2026/6/5	合格	 <p>2026/5/30</p>
54	GX-B1361/26-A-26395	2026/6/5	合格	 <p>2026/5/30</p>



55	GX-B1361/26-A-26396	2026/6/5	合格	
56	GX-B1361/26-A-26397	2026/6/5	合格	



57	GX-B1361/26-A-26398	2026/6/5	合格	 A photograph showing two male technicians in light blue work uniforms. The technician in the foreground is wearing yellow gloves and is focused on adjusting a piece of equipment. The technician in the background is also wearing gloves and is looking towards the equipment. A yellow timestamp '2026/5/30' is visible in the bottom right corner of the photo.
58	GX-B1361/26-A-26399	2026/6/5	合格	 A photograph showing two male technicians in light blue work uniforms. One technician is seated and operating a large, blue and grey industrial machine. The other technician is standing next to him, observing the process. The machine has a label that reads '检测仪器' (Detection Instrument). A yellow timestamp '2026/5/30' is visible in the bottom right corner of the photo.



59	GX-B1361/26-A-26400	2026/6/5	合格	
60	GX-B1361/26-A-26401	2026/6/5	合格	

61	GX-B1361/26-A-26402	2026/6/5	合格	
62	GX-B1361/26-A-26403	2026/6/5	合格	

63	GX-B1361/26-A-26404	2026/6/5	合格	
64	GX-B1361/26-A-26405	2026/6/5	合格	

65	GX-B1361/26-A-26406	2026/6/5	合格	
66	GX-B1361/26-A-26407	2026/6/5	合格	



67	GX-B1361/26-A-26408	2026/6/5	合格	
68	GX-B1361/26-A-26409	2026/6/5	合格	

69	GX-B1361/26-A-26410	2026/6/5	合格	
70	GX-B1361/26-A-26411	2026/6/5	合格	


71	GX-B1361/26-A-26412	2026/6/5	合格	
72	GX-B1361/26-A-26413	2026/6/5	合格	



73	GX-B1361/26-A-26414	2026/6/5	合格	
74	GX-B1361/26-A-26415	2026/6/5	所检项目合格	



75	GX-B1361/26-A-26417	2026/6/5	合格	
76	GX-B1362/23-A-26510	2026/6/5	所检项目合格	

77	GX-B1362/23-A-26511	2026/6/5	所检项目合格	
78	GX-B1362/23-A-26512	2026/6/5	所检项目合格	

79	GX-B1362/23-A-26513	2026/6/5	所检项目合格	
80	GX-B1362/23-A-26514	2026/6/5	所检项目合格	

81	GX-B1362/23-A-26515	2026/6/5	所检项目合格	
82	GX-B1362/23-A-26516	2026/6/5	所检项目合格	

83	GX-B1362/23-A-26517	2026/6/5	所检项目合格	
84	GX-B1362/23-A-26518	2026/6/5	所检项目合格	

85	GX-B1362/23-A-26519	2026/6/5	所检项目合格	
86	GX-B1362/23-A-26520	2026/6/5	所检项目合格	

87	GX-B1362/23-A-26521	2026/6/5	所检项目合格	
88	GX-B1361/26-A-26416	2026/6/5	不合格	