




序号	报告编号	发布日期	结论	影像资料
348	GX-B1308/23-2-26008	2026. 3. 16	综合判定：合格。	
349	GX-B1499/23-2-26044	2026. 3. 16	吨水百米电耗大于0.5 kW•h。除吨水百米电耗超限外，其余所检项目合格。	

350	GX-B1499/23-2-26045	2026. 3. 16	吨水百米电耗大于0.5 kW•h。除吨水百米电耗超限外，其余所检项目合格。	
351	GX-B1499/23-2-26046	2026. 3. 16	吨水百米电耗大于0.5 kW•h。除吨水百米电耗超限外，其余所检项目合格。	



352	GX-B1310/21-2-26150	2026. 3. 28	符合标准要求。	
353	GX-B1310/21-2-26133	2026. 3. 28	符合标准要求。	

354	GX-B1310/21-2-26134	2026. 3. 28	符合标准要求。	
355	GX-B1310/21-2-26135	2026. 3. 28	符合标准要求。	


356	GX-B1309/26-2-26017	2026. 3. 28	所检项目合格。	
357	GX-B1500/26-2-26062	2026. 3. 28	综合判定：合格。	

358	GX-B1500/26-2-26063	2026. 3. 28	综合判定：合格。	
359	GX-B1500/26-2-26064	2026. 3. 28	综合判定：合格。	

360	GX-B1500/26-2-26065	2026. 3. 28	综合判定：合格。	
361	GX-B1500/26-2-26066	2026. 3. 28	综合判定：合格。	

362	GX-B1598/24-2-26134	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为0.96%，小于5%为正常。	
363	GX-B1598/24-2-26135	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为0.85%，小于5%为正常。	

364	GX-B1598/24-2-26136	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为1.58%，小于5%为正常。 。	
365	GX-B1598/24-2-26137	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为1.49%，小于5%为正常。 。	


366	GX-B1598/24-2-26138	2026. 3. 26	实测钢丝绳有效截面积损失百分比最大为1.65%，小于5%为正常。 。	
367	GX-B1451/26-2-26221~26231	2026. 3. 27	本次共检高压开关柜11台，11台高压开关柜所检项目合格。	

368	GX-B1451/26-2-26232~26235	2026. 3. 27	本次共检高压开关柜4台, 4台高压开关柜所检项目合格。	
369	GX-B1451/26-2-26236~26243	2026. 3. 27	本次共检高压开关柜8台, 8台高压开关柜所检项目合格。	

370	GX-B1303/26-2-26001	2026/3/21	综合判定：合格。	
371	<u>GX-B1310/21-2-26141</u>	2026. 3. 26	符合标准要求。	

372	GX-B1310/21-2-26142	2026. 3. 26	符合标准要求。	 03月 05 2026.03.05 星期四 福建省龙岩市连平街芦芝镇X673
373	GX-B1310/21-2-26143	2026. 3. 26	符合标准要求。	 03月 05 2026.03.05 星期四 福建省龙岩市连平街芦芝镇X673

374	GX-B1310/21-2-26144	2026. 3. 26	符合标准要求。		
375	GX-B1310/21-2-26145	2026. 3. 26	符合标准要求。		

376	GX-B1310/21-2-26146	2026. 3. 26	无缺陷迹痕显示。		
377	GX-B1310/21-2-26147	2026. 3. 26	无缺陷迹痕显示。		


378	GX-B1310/21-2-26148	2026. 3. 26	无缺陷迹痕显示。	
379	<u>GX-B1329/26-2-26022~26038</u>	2026. 3. 30	本次共检氧化锌避雷器17组，17组所检项目合格。	


380	GX-B1329/26-2-26064~26071	2026. 3. 30	本次共检氧化锌避雷器8组，8组所检项目合格。	
381	GX-B1322/26-2-26220~26223	2026. 3. 30	本次共检验电力电缆4条，4条所检项目合格。	

382	GX-B1329/26-2-26047~26063	2026. 3. 30	本次共检氧化锌避雷器17组，17组所检项目合格。	 2026/02/27
383	GX-B1350/21-2-26010	2026. 3. 30	本次共检接地装置5处，5处接地装置所检项目合格。	 2026.02.28

384	GX-B1451/26-2-26576~26578	2026. 3. 30	本次共检继电保护装置3台，3台继电保护装置所检项目合格。	
385	GX-B1451/26-2-26129~26147	2026. 3. 30	本次共检高压开关柜19台，19台高压开关柜所检项目合格。	

386	GX-B1451/26-2-26148~26169	2026. 3. 30	本次共检高压开关柜 22台，22台高压开关柜 所检项目合格。		
387	GX-B1329/26-2-26072~26077	2026/3/31	本次共检氧化锌避雷 器6组，6组所检项目 合格。		

388	GX-B1329/26-2-26078~26083	2026/3/31	本次共检氧化锌避雷器6组，6组所检项目合格。		
389	GX-B1350/21-2-26018	2026/3/31	本次共检接地装置4处，4处接地装置所检项目合格。		

390	GX-B1350/21-2-26019	2026/3/31	本次共检接地装置 4处，4处接地装置所 检项目合格。		
391	GX-B1350/21-2-26020	2026/3/31	本次共检接地装置 4处，4处接地装置所 检项目合格。		


392	GX-B1451/26-2-26507~26524	2026/3/31	本次共检高压开关柜18台，18台高压开关柜所检项目合格。		
393	GX-B1451/26-2-26525~26530	2026/3/31	本次共检高压开关柜6台，6台高压开关柜所检项目合格。		



394	<u>GX-B1309/26-2-26012</u>	2026. 3. 30	所检项目合格。	
395	GX-B1500/26-2-26047	2026. 3. 30	综合判定：合格。	

396	GX-B1500/26-2-26048	2026. 3. 30	综合判定：合格。	 A photograph showing two workers in blue uniforms and red hard hats standing next to a large blue industrial machine in a tunnel. The machine has '1500' written on it. The date '2026/03/05' is visible in the bottom right corner of the photo.
397	GX-B1500/26-2-26049	2026. 3. 30	综合判定：合格。	 A photograph showing two workers in blue uniforms and red hard hats standing next to a large blue industrial machine in a tunnel. The machine has '1500' written on it. The date '2026/03/05' is visible in the bottom right corner of the photo.

398	GX-B1309/26-2-26013	2026. 3. 30	所检项目合格。		
399	GX-B1500/26-2-26050	2026. 3. 30	综合判定：合格。		

400	GX-B1500/26-2-26051	2026. 3. 30	综合判定：合格。	 A photograph of two workers in blue uniforms and red hard hats standing next to a large blue industrial machine in a tunnel. Yellow pipes are visible overhead. A date stamp '2026/03/05' is in the bottom right corner.
401	GX-B1500/26-2-26052	2026. 3. 30	综合判定：合格。	 A photograph of two workers in blue uniforms and red hard hats standing next to a large blue industrial machine in a tunnel. Yellow pipes are visible overhead. A date stamp '2026/03/05' is in the bottom right corner.

402	GX-B1309/26-2-26014	2026. 3. 30	所检项目合格。			
403	GX-B1500/26-2-26053	2026. 3. 30	综合判定：合格。			

404	GX-B1500/26-2-26054	2026. 3. 30	综合判定：合格。		
405	GX-B1500/26-2-26055	2026. 3. 30	综合判定：合格。		

406	GX-B1322/26-2-26280~26283	2026. 3. 31	本次共检验电力电缆4条，4条所检项目合格。 。	
407	GX-B1329/26-2-26122~26123	2026. 3. 31	本次共检氧化锌避雷器2组，2组所检项目合格。	

408	<u>GX-B1313/26-2-26141~26148</u>	2026. 3. 30	本次共检电力变压器8台，8台所检项目合格。 。	
409	GX-B1313/26-2-26149~26153	2026. 3. 30	本次共检电力变压器5台，5台所检项目合格。 。	

410	GX-B1313/26-2-26154~26158	2026. 3. 30	本次共检电力变压器5台，5台所检项目合格。 。		
411	GX-B1313/26-2-26159~26160	2026. 3. 30	本次共检电力变压器2台，2台所检项目合格。 。		

412	GX-B1313/26-2-26162~26163	2026. 3. 30	本次共检电力变压器2台，2台所检项目合格。 。	 2026/3/6
413	GX-B1313/26-2-26161	2026. 3. 30	所检项目合格。	 2026/3/6

414	GX-B1313/26-2-26164~26165	2026. 3. 30	本次共检电力变压器2台，2台所检项目合格。 。	
415	GX-B1313/26-2-26052	2026. 3. 30	所检项目合格。	