


序号	报告编号	发布日期	结论	影像资料
33	GX-B1377/22-B-26328~B-26329	2026. 6. 16	所检项目合格	 A photograph showing two male technicians in a laboratory or industrial setting. They are standing next to a large, white, box-like machine with a flat top surface. One technician is leaning over the machine, possibly inspecting or adjusting something on its top. The other technician stands beside him, looking on. The background shows a clean, well-lit room with some equipment and a doorway.
34	GX-B1377/22-B-26316~B-26317	2026. 6. 16	所检项目合格	 A photograph showing the same two male technicians in a similar laboratory or industrial setting. They are now working with a smaller, white, box-like machine. One technician is leaning over the machine, and the other is standing next to him, observing. The background is consistent with the previous image, showing a clean, well-lit room with equipment and a doorway.

35	GX-B1377/22-B-26311	2026. 6. 17	所检项目合格	 2026.6.5
36	GX-B1489/21-B-26079	2026. 6. 17	所检项目合格	 2026.6.6

37	GX-B1489/21-B-26080	2026. 6. 17	所检项目合格	
38	GX-B1378/22-B-26148~B-26153	2026. 6. 17	所检项目合格	

39	GX-B1378/22-B-26154	2026. 6. 17	所检项目合格	 A photograph showing two male technicians in grey uniforms with a logo on the chest. They are standing in a laboratory setting, looking at a piece of equipment. The technician on the left is pointing at the machine. In the background, there is a window with yellow curtains and a white air conditioning unit. A date stamp '2026.6.6' is visible in the bottom right corner of the photo.
40	GX-B1378/22-B-26155~B-26156	2026. 6. 17	所检项目合格	 A photograph showing two male technicians in grey uniforms with a logo on the chest. They are standing at a laboratory bench, looking into a piece of equipment. The technician on the left is pointing at the equipment. The equipment has a logo that reads '中核公信' (CNNC Public Trust). A date stamp '2026.6.6' is visible in the bottom right corner of the photo.

41	GX-B1378/22-B-26157	2026. 6. 17	所检项目合格	 2026.6.6
42	GX-B1377/22-B-26313	2026. 6. 18	所检项目合格	 2026.6.9

43	GX-B1377/22-B-26314~B-26315	2026. 6. 18	所检项目合格	 A photograph showing two men in a laboratory setting. They are standing behind a piece of scientific equipment, possibly a spectrophotometer or a similar analytical instrument. The man on the left is wearing a grey button-down shirt, and the man on the right is wearing a light blue button-down shirt. They appear to be looking at the equipment or a screen. The background shows a window with yellow curtains and some lab supplies on a table.
44	GX-B1378/22-B-26182~B-26183	2026. 6. 23	所检项目合格	 A photograph showing two men in a laboratory setting. They are standing in front of a large piece of scientific equipment, possibly a furnace or a similar analytical instrument. The man on the left is wearing a light blue button-down shirt, and the man on the right is wearing a grey button-down shirt. They appear to be looking at the equipment or a screen. The background shows a window with yellow curtains and some lab supplies on a table.

45	GX-B1378/22-B-26184~B-26185	2026. 6. 23	所检项目合格	 A photograph showing two men in light blue lab coats standing in a laboratory. They are positioned behind a white piece of equipment, possibly a spectrophotometer or a similar analytical instrument. The man on the left is looking at the equipment, while the man on the right is looking down at something in his hands. The background features a window with yellow curtains and some laboratory furniture like a chair and a table. A small timestamp '2026.6.15' is visible in the bottom right corner of the photo.
46	GX-B1378/22-B-26186~B-26193	2026. 6. 23	所检项目合格	 A photograph showing two men in light blue lab coats in a laboratory setting, similar to the one above. They are standing behind a white piece of equipment. The man on the left is looking at the equipment, and the man on the right is looking down. The background includes a window with yellow curtains and laboratory furniture. A small timestamp '2026.6.11' is visible in the bottom right corner of the photo.

47	GX-B1377/22-B-26322~B-26323	2026. 6. 23	所检项目合格	 A photograph showing two men in light blue lab coats working with a large, grey industrial machine. The man on the left is looking down at the machine, while the man on the right is looking towards the camera. The machine has a yellow warning label. The background shows a room with orange curtains and some white containers on a table. A timestamp '2026.6.12' is visible in the bottom right corner of the photo.
48	GX-B1377/22-B-26318~B-26321	2026. 6. 23	所检项目合格	 A photograph showing two men in light blue lab coats inspecting a large, grey industrial machine. The man on the left is looking at the machine, while the man on the right is looking towards the camera. The machine has a yellow warning label. The background shows a room with orange curtains and some white containers on a table. A timestamp '2026.6.12' is visible in the bottom right corner of the photo.

49	GX-B1378/22-B-26167	2026. 6. 24	所检项目合格	
50	GX-B1378/22-B-26168	2026. 6. 24	所检项目合格	

51	GX-B1378/22-B-26170~B-26171	2026. 6. 24	所检项目合格		
52	GX-B1378/22-B-26172~B-26174	2026. 6. 24	所检项目合格		

53	GX-B1377/22-B-26318~B-26321	2026. 6. 23	所检项目合格	
----	-----------------------------	-------------	--------	---