

序号	报告编号	发布日期	结论	影像资料
3 1 6	GX-B1363/25-A-26243	2026/6/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 1 7	GX-B1363/25-A-26244	2026/6/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
318	GX-B1363/25-A-26240	2026/6/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 1 9	GX-B1363/25-A-26241	2026/6/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 2 0	GX-B1363/25-A-26242	2026/6/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 2 1	GX-B1538/26-A-26065	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 2 2	GX-B1538/26-A-26066	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 2 3	GX-B1538/26-A-26067	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 2 4	GX-B1538/26-A-26068	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 2 5	GX-B1538/26-A-26069	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 2 6	GX-B1538/26-A-26070	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 2 7	GX-B1538/26-A-26071	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
328	GX-B1538/26-A-26072	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 2 9	GX-B1538/26-A-26073	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
330	GX-B1538/26-A-26074	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
331	GX-B1538/26-A-26075	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 3 2	GX-B1538/26-A-26076	2026/6/17	所检项目合格。	 A photograph showing two male technicians in grey uniforms operating a large industrial machine. The machine has a control panel with a screen and several buttons. A yellow warning sign with a triangle and the text '注意高温' (Caution High Temperature) is visible on the machine. The date '2026.06.11' is printed in orange in the bottom right corner of the photo. The technician on the right has a logo on his sleeve that says '中国石化' (China Petrochemical).

序号	报告编号	发布日期	结论	影像资料
3 3 3	GX-B1538/26-A-26077	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 3 4	GX-B1538/26-A-26078	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
335	GX-B1538/26-A-26079	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
336	GX-B1538/26-A-26080	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
337	GX-B1538/26-A-26081	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
338	GX-B1538/26-A-26082	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
339	GX-B1538/26-A-26083	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
340	GX-B1538/26-A-26084	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 4 1	GX-B1538/26-A-26085	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 4 2	GX-B1538/26-A-26086	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 4 3	GX-B1538/26-A-26087	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 4 5	GX-B1364/26-A-26488	2026/6/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 4 6	GX-B1364/26-A-26464	2026/6/17	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
3 4 7	GX-B1367/26-A-26047	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 4 8	GX-B1367/26-A-26048	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 4 9	GX-B1367/26-A-26049	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
350	GX-B1367/26-A-26050	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
351	GX-B1367/26-A-26051	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 5 2	GX-B1367/26-A-26052	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 5 3	GX-B1538/26-A-26092	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 5 4	GX-B1538/26-A-26093	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
355	GX-B1538/26-A-26088	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 5 6	GX-B1538/26-A-26090	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 5 7	GX-B1538/26-A-26091	2026/6/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
358	GX-B1364/26-A-26514	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
359	GX-B1364/26-A-26513	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
360	GX-B1364/26-A-26512	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
361	GX-B1364/26-A-26511	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 6 2	GX-B1364/26-A-26510	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
363	GX-B1364/26-A-26509	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
364	GX-B1364/26-A-26508	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
365	GX-B1364/26-A-26507	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
366	GX-B1364/26-A-26499	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 6 7	GX-B1538/26-A-26094	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
368	GX-B1365/25-A-26057	2026/6/22	所检项目全部合格。	


序号	报告编号	发布日期	结论	影像资料
369	GX-B1366/25-A-26087	2026/6/22	所检项目全部合格。	


序号	报告编号	发布日期	结论	影像资料
370	GX-B1363/25-A-26249	2026/6/23	所检项目合格。	 A photograph showing two men in grey uniforms inspecting a large industrial furnace. The furnace has a control panel with red and blue buttons. The date stamp '2026.06.18' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
3 7 1	GX-B1363/25-A-26250	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 7 2	GX-B1363/25-A-26251	2026/6/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 7 3	GX-B1508/26-A-26013	2026/6/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3 7 4	GX-B1508/26-A-26014	2026/6/22	阻燃性能不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
375	GX-B1508/26-A-26015	2026/6/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
376	GX-B1508/26-A-26016	2026/6/22	阻燃性能不合格；其余所检项目合格。	