

序号	报告编号	发布日期	结论	影像资料	
204	GX-B1309/26-5-26016	2026. 6. 18	所检项目合格。		
205	GX-B1500/26-5-26051	2026. 6. 18	综合判定：合格。		

206	GX-B1500/26-5-26052	2026. 6. 18	综合判定：合格。			
207	GX-B1500/26-5-26053	2026. 6. 18	综合判定：合格。			

208	GX-B1500/26-5-26054	2026. 6. 18	综合判定：合格。			
209	GX-B1500/26-5-26055	2026. 6. 18	综合判定：合格。			

210	GX-B1309/26-5-26017	2026. 6. 18	所检项目合格。			
211	GX-B1500/26-5-26056	2026. 6. 18	综合判定：合格。			

212	GX-B1500/26-5-26057	2026. 6. 18	综合判定：合格。			
213	GX-B1500/26-5-26058	2026. 6. 18	综合判定：合格。			

214	GX-B1500/26-5-26059	2026. 6. 18	综合判定：合格。		 2026/5/29	
215	GX-B1309/26-5-26018	2026. 6. 18	所检项目合格。		 2026/5/29	

216	GX-B1500/26-5-26060	2026. 6. 18	综合判定：合格。		
217	GX-B1500/26-5-26061	2026. 6. 18	综合判定：合格。		

218	GX-B1500/26-5-26062	2026. 6. 18	综合判定：合格。		
219	GX-B1500/26-5-26063	2026. 6. 18	综合判定：合格。		

220	GX-B1309/26-5-26019	2026. 6. 18	所检项目合格。		
221	GX-B1500/26-5-26064	2026. 6. 18	综合判定：合格。		

222	GX-B1500/26-5-26065	2026. 6. 18	综合判定：合格。		
223	GX-B1500/26-5-26066	2026. 6. 18	综合判定：合格。		

224	GX-B1500/26-5-26067	2026. 6. 18	综合判定：合格。	
225	GX-B1309/26-5-26020	2026. 6. 18	所检项目合格。	

226	GX-B1500/26-5-26068	2026. 6. 18	综合判定：合格。		
227	GX-B1500/26-5-26069	2026. 6. 18	综合判定：合格。		

228	GX-B1500/26-5-26070	2026. 6. 18	综合判定：合格。			
229	GX-B1500/26-5-26071	2026. 6. 18	综合判定：合格。			


230	GX-B1500/26-5-26072	2026. 6. 18	综合判定：合格。			
231	GX-B1309/26-5-26021	2026. 6. 18	所检项目合格。			


232	GX-B1500/26-5-26073	2026. 6. 18	综合判定：合格。			
233	GX-B1500/26-5-26074	2026. 6. 18	综合判定：合格。			

234	GX-B1500/26-5-26075	2026. 6. 18	综合判定：合格。			
235	GX-B1500/26-5-26076	2026. 6. 18	综合判定：合格。			

236	GX-B1495/26-5-26720~26724	2026年6月24日	本次共检高压开关柜5台, 5台高压开关柜所检项目合格。	 A worker wearing a blue jacket, red helmet, and orange gloves is inspecting a high-voltage switchgear cabinet. The worker is standing next to the cabinet, which has its door open, revealing internal components. A timestamp '2026.03.16' is visible in the bottom right corner of the photo.
237	GX-B1321/26-5-26593~26596	2026年6月21日	本次共检电力电缆4条, 4条电力电缆所检项目合格。	 A worker wearing a blue jacket, red helmet, and orange gloves is kneeling on a green patterned floor, inspecting power cables. The worker is using a red tool to check the cables. The background is a blue wall. A timestamp '2026.03.16' is visible in the bottom right corner of the photo.

238	GX-B1312/26-5-26161	2026. 6. 19	所检项目合格。	
239	GX-B1312/26-5-26342~26343	2026. 6. 18	本次共检电力变压器2台，2台电力变压器所检项目合格。	


240	GX-B1495/26-5-261040~261053	2026. 6. 22	本次共检防爆型高压 配电装置14台, 14台防 爆型高压配电装置所 检项目合格。		 2026.3.6	
241	GX-B1321/26-5-26625~26638	2026. 6. 23	本次共检电力电缆14 条, 14条电力电缆所 检项目合格。		 2026.3.5	

242	GX-B1321/26-5-26657~26666	2026. 6. 23	本次共检电力电缆10条，10条电力电缆所检项目合格。		 2026.3.7	
243	GX-B1323/26-5-26217~26219	2026. 6. 23	所检项目合格。		 2026.3.5	

244	GX-B1323/26-5-26214~26216	2026. 6. 23	所检项目合格。		
245	GX-B1323/26-5-26209~26213	2026. 6. 23	所检项目合格。		


246	GX-B1321/26-5-26667~26677	2026. 6. 23	本次共检电力电缆11条，11条电力电缆所检项目合格。	
247	GX-B1495/26-5-261094~261098	2026. 6. 23	本次共检高压开关柜5台，5台高压开关柜所检项目合格。	


248	GX-B1495/26-5-261062~261080	2026. 6. 23	本次共检高压开关柜19台, 19台高压开关柜所检项目合格。		 2026.3.15
249	GX-B1495/26-5-261056~261061	2026. 6. 23	本次共检防爆型高压配电装置6台, 6台防爆型高压配电装置所检项目合格。		 2026.3.18

250	GX-B1495/26-5-261055	2026. 6. 21	所检项目合格。		
251	GX-B1495/26-5-261054	2026. 6. 21	所检项目合格。		

252	GX-B1495/26-5-261099~261114	2026. 6. 23	本次共检高压开关柜 16台, 16台高压开关柜 所检项目合格。	
253	GX-B1323/26-5-26208	2026. 6. 21	所检项目合格。	

254	GX-B1312/26-5-26359	2026. 6. 21	所检项目合格。	
255	GX-B1321/26-5-26614~26624	2026. 6. 23	本次共检电力电缆11条，11条电力电缆所检项目合格。	

256	GX-B1321/26-5-26639~26640	2026. 6. 23	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	 2026.3.9
257	GX-B1321/26-5-26641~26646	2026. 6. 22	本次共检电力电缆 6条，6条电力电缆所 检项目合格。	 2026.3.13


258	GX-B1495/26-5-261039	2026. 6. 23	所检项目合格。	
259	GX-B1321/26-5-26647~26656	2026. 6. 23	本次共检电力电缆10条，10条电力电缆所检项目合格。	

260	GX-B1495/26-5-26629~26642	2026. 6. 23	本次共检高压开关柜 14台, 14台高压开关柜 所检项目合格。	
261	GX-B1321/26-5-26678	2026. 6. 24	所检项目合格。	

262	GX-B1404/26-5-26011	2026. 6. 25	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。		
263	GX-B1404/26-5-26012	2026. 6. 25	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。		

264	GX-B1404/26-5-26013	2026. 6. 25	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
265	GX-B1404/26-5-26014	2026. 6. 25	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

266	GX-B1495/26-5-26911~26934	2026. 6. 25	本次共检高压开关设备24台，24台高压开关设备所检项目合格。	
267	GX-B1312/26-5-26381~26382	2026. 6. 25	本次共检防爆干式变压器2台，2台防爆干式变压器所检项目合格。	


268	GX-B1312/26-5-26376~26377	2026. 6. 25	本次共检防爆干式变压器2台，2台防爆干式变压器所检项目合格。		 2026.3.6	
269	GX-B1312/26-5-26378~26380	2026. 6. 25	本次共检防爆干式变压器3台，3台防爆干式变压器所检项目合格。		 2026.3.5	

270	GX-B1312/26-5-26375	2026. 6. 25	所检项目合格。	
271	GX-B1312/26-5-26372~26374	2026. 6. 25	本次共检防爆干式变压器3台，3台防爆干式变压器所检项目合格。	

272	GX-B1312/26-5-26368~26371	2026. 6. 25	本次共检防爆干式变压器4台，4台防爆干式变压器所检项目合格。	
273	GX-B1312/26-5-26364~26367	2026. 6. 25	本次共检电力变压器4台，4台电力变压器所检项目合格。	

274	GX-B1312/26-5-26362~26363	2026. 6. 25	本次共检电力变压器2台，2台电力变压器所检项目合格。	 2026.3.13
275	GX-B1312/26-5-26360~26361	2026. 6. 25	本次共检电力变压器2台，2台电力变压器所检项目合格。	 2026.3.17

276	GX-B1312/26-5-26358	2026. 6. 25	所检项目合格。	 A worker wearing a grey jacket, orange helmet, and safety glasses is working on electrical equipment. The date 2026.3.17 is visible in the bottom right corner of the image.
277	GX-B1329/26-5-26470~26471	2026. 6. 23	本次共检氧化锌避雷器2组，2组氧化锌避雷器所检项目合格。	 A worker wearing a red suit, red helmet, and safety glasses is standing in a tunnel next to electrical equipment. The date 2026.06.14 is visible in the bottom right corner of the image.

278	GX-B1451/26-5-262800~262801	2026. 6. 23	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	
279	GX-B1451/26-5-262802~262803	2026. 6. 23	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	

280	GX-B1451/26-5-262804~262805	2026. 6. 23	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	
281	GX-B1313/26-5-26720 ~ 26721	2026. 6. 23	本次共检电力变压器2台，2台电力变压器所检项目合格。	

282	GX-B1313/26-5-26722~26723	2026. 6. 23	本次共检电力变压器2台，2台电力变压器所检项目合格。		 2026/06/10
283	GX-B1313/26-5-26724~26725	2026. 6. 23	本次共检电力变压器2台，2台电力变压器所检项目合格。		 2026/06/11


284	GX-B1313/26-5-26726~26727	2026. 6. 23	本次共检电力变压器2台，2台电力变压器所检项目合格。	
285	GX-B1313/26-5-26728~26729	2026. 6. 23	本次共检电力变压器2台，2台电力变压器所检项目合格。	

286	GX-B1350/21-5-26220	2026. 6. 22	所检项目合格。		
287	GX-B1350/21-5-26221	2026. 6. 22	所检项目合格。		

288	GX-B1350/21-5-26222	2026. 6. 22	所检项目合格。		
289	GX-B1350/21-5-26223	2026. 6. 22	所检项目合格。		

290	GX-B1350/21-5-26224	2026. 6. 22	所检项目合格。		
291	GX-B1322/26-5-26940~26943	2026. 6. 22	本次共检电力电缆 4条，4条电力电缆所 检项目合格。		

292	GX-B1322/26-5-26944~26945	2026. 6. 22	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	
293	GX-B1322/26-5-26946~26949	2026. 6. 22	本次共检电力电缆 4条，4条电力电缆所 检项目合格。	

294	GX-B1322/26-5-26950~26951	2026. 6. 22	本次共检电力电缆 2条，2条电力电缆所 检项目合格。	
295	:GX-B1598/24-5-26180	2026年6月26日	实测钢丝绳有效截面 积损失百分比最大为 3.87%，小于5%为正常 。	

296	:GX-B1598/24-5-26181	2026年6月26日	实测钢丝绳有效截面积损失百分比最大为4.68%，小于5%为正常。 。			
297	GX-B1598/24-5-26182	2026年6月26日	实测钢丝绳有效截面积损失百分比最大为3.55%，小于5%为正常。 。			

298	GX-B1598/24-5-26183	2026年6月26日	实测钢丝绳有效截面 积损失百分比最大为 3.60%，小于5%为正常 。		
299	GX-B1598/24-5-26184	2026年6月26日	实测钢丝绳有效截面 积损失百分比最大为 4.61%，小于5%为正常 。		

300	GX-B1598/24-5-26185	2026年6月26日	实测钢丝绳有效截面积损失百分比最大为3.89%，小于5%为正常。 。	
301	GX-B1598/24-5-26186	2026年6月26日	实测钢丝绳有效截面积损失百分比最大为3.69%，小于5%为正常。 。	

302	GX-B1598/24-5-26187	2026年6月26日	实测钢丝绳有效截面积损失百分比最大为3.84%，小于5%为正常。 。	
303	GX-B1598/24-5-26188	2026年6月26日	实测钢丝绳有效截面积损失百分比最大为3.63%，小于5%为正常。 。	

304	GX-B1598/24-5-26189	2026年6月26日	实测钢丝绳有效截面积损失百分比最大为3.75%，小于5%为正常。 。	
-----	---------------------	------------	---------------------------------------	---