


序号	报告编号	发布日期	结论	影像资料
250	GX-B1308/26-2-26012	2026. 6. 24	所检项目合格。	 施工记录 天气: 阴 22℃ 东南风5级 湿度11% 经纬度: 109.384423 纬度: 38.742073 地址: 鄂尔多斯市乌审旗在煤炭有限责任公司巴彦高勒煤矿附近 工程名称: 我的工程 时间: 2026-05-19 16:33:53
251	GX-B1308/26-2-26009	2026. 6. 24	所检项目合格。	 施工记录 天气: 阴 23℃ 东南风5级 湿度31% 经纬度: 109.398466 纬度: 38.742113 地址: 鄂尔多斯市乌审旗在煤炭有限责任公司巴彦高勒煤矿附近 工程名称: 我的工程 时间: 2026-05-19 16:33:38

252	GX-B1308/26-2-26010	2026. 6. 24	所检项目合格。	
253	GX-B1499/26-2-26071	2026. 6. 25	所检项目合格	

254	GX-B1499/26-2-26072	2026. 6. 25	所检项目合格	
255	GX-B1499/26-2-26073	2026. 6. 25	1. 泵工况点效率小于 额定效率的80%; 2. 吨水百米电耗大于 0. 5kW · h。 除上述两项外, 其余 所检项目合格。	



256	GX-B1499/26-2-26074	2026. 6. 25	1. 泵工况点效率小于额定效率的80%; 2. 吨水百米电耗大于0. 5kW · h。 除上述两项外, 其余所检项目合格。	
257	GX-B1499/26-2-26075	2026. 6. 25	1. 泵工况点效率小于额定效率的80%; 2. 吨水百米电耗大于0. 5kW · h。 除上述两项外, 其余所检项目合格。	


258	GX-B1301-26-2-26008	2026. 6. 25	综合判定:合格。	 施工记录 经度: 109.3980567 纬度: 38.7425171 地址: 鄂尔多斯市乌审旗在煤炭有限责任公司巴彦高勒煤矿附近 工程名称: 黄陶勒盖煤矿 时间: 2026-06-11
259	GX-B1301-26-2-26009	2026. 6. 25	综合判定:合格。	 施工记录 地址: 鄂尔多斯市乌审旗在煤炭有限责任公司巴彦高勒煤矿附近 工程名称: 黄陶勒盖煤矿 时间: 2026-06-11

260	GX-B1301-26-2-26010	2026. 6. 25	综合判定:合格。	 施工记录 地 址: 鄂尔多斯市乌审旗在煤炭有限责任公司巴彦高勒煤矿附近 工程名称: 黄陶勒盖煤矿 时 间: 2026-06-12
261	GX-B1301-26-2-26011	2026. 6. 25	综合判定:合格。	 施工记录 地 址: 鄂尔多斯市乌审旗在煤炭有限责任公司巴彦高勒煤矿附近 工程名称: 黄陶勒盖煤矿 时 间: 2026-06-15

262	GX-B1598/24-2-26248	2026. 6. 26	实测钢丝绳有效截面 积损失百分比最大为 1.17%，小于5%为正常 。	
263	GX-B1598/24-2-26249	2026. 6. 26	实测钢丝绳有效截面 积损失百分比最大为 1.33%，小于5%为正常 。	

264	GX-B1598/24-2-26250	2026. 6. 26	实测钢丝绳有效截面 积损失百分比最大为 1. 49%， 小于5%为正常 。	
265	GX-B1598/24-2-26251	2026. 6. 26	实测钢丝绳有效截面 积损失百分比最大为 1. 38%， 小于5%为正常 。	


266	GX-B1598/24-2-26252	2026. 6. 26	实测钢丝绳有效截面 积损失百分比最大为 0.84%，小于5%为正常 。	
267	GX-B1598/24-2-26253	2026. 6. 26	实测钢丝绳有效截面 积损失百分比最大为 0.69%，小于5%为正常 。	

268	GX-B1308/26-2-26011	2026. 6. 24	综合判定：合格。	 施工记录 天气: 晴 22°C 东南风 5级 湿度 37% 站 址: 109.538423 地 址: 38.562293 地 址: 鄂尔多斯市乌审旗在深和隆源任公司巴彦高勒 工程名称: 煤的工程 时 间: 2026-05-19 16:13:53  2026-05-19
-----	---------------------	-------------	----------	---

270	GX-B1404/26-2-26004	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
271	GX-B1404/26-2-26005	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

272	GX-B1404/26-2-26006	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
273	GX-B1404/26-2-26007	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

274	GX-B1404/26-2-26008	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	 06月 12 2026.06.12 星期五 内蒙古自治区鄂尔多斯市乌审旗 兰陶勒盖镇
275	GX-B1404/26-2-26009	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	 06月 12 2026.06.12 星期五 内蒙古自治区鄂尔多斯市乌审旗 兰陶勒盖镇

276	GX-B1404/26-2-26010	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
277	GX-B1404/26-2-26011	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

278	GX-B1404/26-2-26012	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
279	GX-B1404/26-2-26013	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

280	GX-B1404/26-2-26014	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
281	GX-B1404/26-2-26015	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	


282	GX-B1404/26-2-26016	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
283	GX-B1404/26-2-26017	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

284	GX-B1404/26-2-26018	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
285	GX-B1404/26-2-26019	2026. 6. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

286	GX-B1354/26-2-26004	2026. 6. 26	合格。	
287	GX-B1354/26-2-26005	2026. 6. 26	合格。	


288	GX-B1310/21-2-26246	2026/6/27	符合标准要求。	 2026/06/13
289	GX-B1310/21-2-26247	2026/6/27	符合标准要求。	 2026/06/13

290	GX-B1310/21-2-26248	2026/6/27	符合标准要求。	 A photograph showing two workers in a dark industrial setting at night. The worker in the foreground is wearing a red hard hat, safety glasses, and a dark jacket with reflective stripes. The worker in the background is also wearing a red hard hat and a light blue shirt. The date 2026/06/13 is visible in the bottom right corner of the image.
291	GX-B1310/21-2-26249	2026/6/27	符合标准要求。	 A photograph showing two workers in a dark industrial setting at night. They are wearing reflective safety gear, including hard hats and high-visibility vests. The date 2026/06/14 is visible in the bottom right corner of the image.

292	GX-B1310/21-2-26250	2026/6/27	符合标准要求。		
293	GX-B1310/21-2-26251	2026/6/27	符合标准要求。		

294	GX-B1310/21-2-26252	2026/6/27	符合标准要求。	 A photograph showing two workers in red hard hats and blue uniforms with reflective stripes. They are standing in a dark industrial environment, possibly a tunnel or underground facility. The worker in the foreground is wearing glasses and a face mask. The date 2026/06/12 is visible in the bottom right corner of the image.
295	GX-B1310/21-2-26253	2026/6/27	符合标准要求。	 A photograph showing two workers in red hard hats and blue uniforms. They are standing in a dark industrial environment, possibly a tunnel or underground facility. The worker in the foreground is wearing glasses and a face mask. The date 2026/06/12 is visible in the bottom right corner of the image.

296	GX-B1310/21-2-26235	2026/6/27	符合标准要求。	 06月 11 2026.06.11 星期四 内蒙古自治区鄂尔多斯市达拉特旗 三陶铝业氧化铝生产项目2504号
297	GX-B1310/21-2-26236	2026/6/27	符合标准要求。	 06月 12 2026.06.12 星期五 内蒙古自治区鄂尔多斯市达拉特旗 三陶铝业氧化铝生产项目2504号

298	GX-B1310/21-2-26237	2026/6/27	符合标准要求。	
299	GX-B1310/21-2-26238	2026/6/27	符合标准要求。	

302	GX-B1428/21-2-26239	2026/6/27	无缺陷迹痕显示。	
303	GX-B1428/21-2-26240	2026/6/27	无缺陷迹痕显示。	

304	GX-B1499/26-2-26057	2026. 6. 27	1. 泵工况点效率小于额定效率的80%； 2. 吨水百米电耗大于0.5kW·h； 3. 水泵性能曲线上水泵工作效率均低于额定效率80%，未形成工业利用区。除上述问题外，其余所检项目合格。	 地点：331盘区面后4号排水点 日期：2026/4/25 星期六
305	GX-B1499/26-2-26058	2026. 6. 27	1. 泵工况点效率小于额定效率的80%； 2. 吨水百米电耗大于0.5kW·h； 3. 水泵性能曲线上水泵工作效率均低于额定效率80%，未形成工业利用区。除上述问题外，其余所检项目合格。	 地点：331盘区面后4号排水点 日期：2026/4/25 星期六

306	GX-B1499/26-2-26059	2026. 6. 27	1. 泵工况点效率小于额定效率的80%； 2. 吨水百米电耗大于0.5kW·h； 3. 水泵性能曲线上水泵工作效率均低于额定效率80%，未形成工业利用区。除上述问题外，其余所检项目合格。	 地点：331盘区面后4#排水点 日期：2026/4/25 星期六
307	GX-B1499/26-2-26060	2026. 6. 27	1. 泵工况点效率小于额定效率的80%； 2. 吨水百米电耗大于0.5kW·h； 3. 水泵性能曲线上水泵工作效率均低于额定效率80%，未形成工业利用区。除上述问题外，其余所检项目合格。	 地点：331盘区面后4#排水点 日期：2026/4/25 星期六

308	GX-B1499/26-2-26061	2026. 6. 27	1. 泵工况点效率小于额定效率的80%； 2. 吨水百米电耗大于0.5kW·h； 3. 水泵性能曲线上水泵工作效率均低于额定效率80%，未形成工业利用区。除上述问题外，其余所检项目合格。	 地点：331盘区面后4#排水点 日期：2026/4/25 星期六
309	GX-B1499/26-2-26062	2026. 6. 27	1. 泵工况点效率小于额定效率的80%； 2. 吨水百米电耗大于0.5kW·h； 3. 水泵性能曲线上水泵工作效率均低于额定效率80%，未形成工业利用区。除上述问题外，其余所检项目合格。	 地点：331盘区面后4#排水点 日期：2026/4/25 星期六

310	GX-B1499/26-2-26063	2026. 6. 27	1. 泵工况点效率小于额定效率的80%； 2. 吨水百米电耗大于0.5kW·h； 3. 水泵性能曲线上水泵工作效率均低于额定效率80%，未形成工业利用区。除上述问题外，其余所检项目合格。	 地点：331盘区面后4#排水点 日期：2026/4/25 星期六
311	GX-B1416/22-2-26008	2026/6/27	综合判定：合格。	 2026/06/13

312	GX-B1416/22-2-26009	2026/6/27	综合判定：合格。	 2026/06/13
313	GX-B1416/22-2-26010	2026/6/27	综合判定：合格。	 2026/06/13

314	GX-B1416/22-2-26011	2026/6/27	综合判定：合格。	 2026/06/14
315	GX-B1416/22-2-26012	2026/6/27	综合判定：合格。	 2026/06/13

316	GX-B1416/22-2-26013	2026/6/27	综合判定：合格。	 2026/06/12
317	GX-B1416/22-2-26014	2026/6/27	综合判定：合格。	 2026/06/12

318	GX-B1416/22-2-26015	2026/6/27	综合判定：合格。	
319	GX-B1306/23-2-26007	2026/6/27	综合判定：合格。	

320	GX-B1306/23-2-26008	2026/6/27	综合判定：合格。	
321	GX-B1301/26-2-26007	2026/6/27	所检项目合格。	