


序号	报告编号	发布日期	结论	影像资料
322	GX-B1306/23-2-26003	2026. 6. 29	综合判定：合格。	 施工记录 经纬度: 109.399734 高度: 38.742020 地址: 鄂尔多斯市乌审旗在煤炭有限责任公司巴彦高勒煤矿附近 工程名称: 黄陶勒盖煤矿 时间: 2026-06-12
323	GX-B1306/23-2-26004	2026. 6. 29	综合判定：合格。	 施工记录 经纬度: 109.399714 高度: 38.742008 地址: 鄂尔多斯市乌审旗在煤炭有限责任公司巴彦高勒煤矿附近 工程名称: 黄陶勒盖煤矿 时间: 2026-06-12

324	GX-B1306/23-2-26005	2026. 6. 29	综合判定：合格。	
325	GX-B1306/23-2-26006	2026. 6. 29	综合判定：合格。	

326	GX-B1306/23-2-26009	2026. 6. 29	综合判定：合格。	 A photograph showing two workers in blue uniforms and red helmets standing next to a red equipment unit. A yellow toolbox is on the ground. The date 2026/06/15 is visible in the bottom right corner.
327	GX-B1306/23-2-26010	2026. 6. 29	综合判定：合格。	 A photograph showing two workers in blue uniforms and red helmets standing next to a red equipment unit. A yellow toolbox is on the ground. The date 2026/06/15 is visible in the bottom right corner.

328	GX-B1418/26-2-26002	2026. 6. 29	综合判定：合格。			
329	GX-B1418/26-2-26004	2026. 6. 29	综合判定：合格。			

330	GX-B1418/26-2-26003	2026. 6. 29	综合判定：合格。	
331	GX-B1308/26-2-26014	2026. 6. 30	综合判定：合格。	

332	GX-B1308/26-2-26015	2026. 6. 30	综合判定：合格。	
333	GX-B1451/26-2-261041~261043	2026/6/30	本次共检高压开关柜3台，3台高压开关柜所检项目合格。	

334	GX-B1451/26-2-261044~261046	2026/6/30	本次共检继电保护装置3台，3台继电保护装置所检项目合格。	
335	GX-B1329/26-2-26160~26161	2026/6/30	本次共检氧化锌避雷器2组，2组所检项目合格。	

336	GX-B1313/26-2-26346	2026/6/29	所检项目合格。	
-----	---------------------	-----------	---------	---