

序号	报告编号	发布日期	结论	影像资料
1	GX-B1304/26-3-26016	2026年7月1日	综合判定：合格。	
2	GX-B1304/26-3-26017	2026年7月1日	综合判定：合格。	

3	GX-B1304/26-3-26018	2026年7月1日	综合判定：合格。	
4	GX-B1310/21-3-26396	2026. 7. 1	符合标准要求	

5	GX-B1310/21-3-26397	2026. 7. 1	符合标准要求	
6	GX-B1322/26-3-26401~26404	2026. 7. 2	所检项目合格。	

7	GX-B1322/26-3-26405~26406	2026. 7. 2	所检项目合格。		
8	GX-B1322/26-3-26407~26408	2026. 7. 2	所检项目合格。		


9	GX-B1322/26-3-26409~26410	2026. 7. 2	所检项目合格。	
10	GX-B1322/26-3-26399~26400	2026. 7. 2	所检项目合格。	

11	GX-B1322/26-3-26411~26412	2026. 7. 2	所检项目合格。	 A worker wearing a red helmet, safety glasses, and a light-colored work jacket is working on a piece of machinery. The worker is holding a tool or wire. A date stamp '2026/5/11' is visible in the bottom right corner of the image.
12	GX-B1304/26-3-26015	2026. 7. 2	综合判定：合格。	 A worker wearing a red helmet and safety gear is working on a large, blue industrial machine. The worker is standing on a yellow platform. A date stamp '2026.04.23' is visible in the bottom right corner of the image.

13	GX-B1322/26-3-26413	2026. 7. 2	所检项目合格。	
14	GX-B1322/26-3-26419~26422	2026. 7. 2	所检项目合格。	

15	GX-B1301/26-3-26006	2026年7月3日	综合判定:合格。	
16	GX-B1612/26-3-26014	2026年7月3日	所检项目合格。	

17	GX-B1612/26-3-26015	2026年7月3日	所检项目合格。	 A man wearing a red hard hat and a grey work jacket stands next to a green truck. The truck has some text on its side, including "安能" and "安能书柜". A yellow timestamp "2026.4.29" is visible in the bottom right corner of the photo.
18	GX-B1612/26-3-26016	2026年7月3日	所检项目合格。	 A close-up view of the side of a green truck, showing the door and window area. A yellow timestamp "2026.4.29" is visible in the bottom right corner of the photo.

19	GX-B1612/26-3-26017	2026年7月3日	所检项目合格。	
20	GX-B1612/26-3-26018	2026年7月3日	所检项目合格。	

21	GX-B1612/26-3-26019	2026年7月3日	所检项目合格。	
22	GX-B1612/26-3-26020	2026年7月3日	所检项目合格。	

23	GX-B1612/26-3-26021	2026年7月3日	所检项目合格。	
24	GX-B1612/26-3-26022	2026年7月3日	所检项目合格。	


25	GX-B1612/26-3-26023	2026年7月3日	所检项目合格。	
26	GX-B1612/26-3-26024	2026年7月3日	所检项目合格。	


27	GX-B1612/26-3-26025	2026年7月3日	所检项目合格。	
28	GX-B1612/26-3-26026	2026年7月3日	所检项目合格。	


29	GX-B1612/26-3-26027	2026年7月3日	所检项目合格。	
30	GX-B1612/26-3-26028	2026年7月3日	所检项目合格。	


31	GX-B1612/26-3-26029	2026年7月3日	所检项目合格。	
32	GX-B1612/26-3-26030	2026年7月3日	所检项目合格。	

33	GX-B1612/26-3-26031	2026年7月3日	所检项目合格。	
34	GX-B1612/26-3-26032	2026年7月3日	所检项目合格。	

35	GX-B1310/21-3-26431	2026. 7. 5	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 A worker wearing a blue uniform, a red helmet, and safety glasses is inspecting a structure. The worker is holding a device in their hands. The background shows a blue wall and some yellow and black striped safety tape. The date 2026.06.22 is visible in the bottom right corner of the image.
36	GX-B1598/24-3-26082	2026. 7. 5	实测钢丝绳有效截面积损失百分比最大为 2.57%，小于5%为正常。 。	 A worker wearing an orange uniform, a yellow helmet, and safety glasses is inspecting a structure. The worker is holding a device in their hands. The background shows a wooden structure and some yellow and black striped safety tape. The date 2026.04.28 is visible in the bottom right corner of the image.

37	GX-B1598/24-3-26083	2026. 7. 5	实测钢丝绳有效截面 积损失百分比最大为 2. 74%， 小于5%为正常 。	
38	GX-B1598/24-3-26084	2026. 7. 5	实测钢丝绳有效截面 积损失百分比最大为 2. 61%， 小于5%为正常 。	

41	GX-B1310/21-3-26406	2026. 7. 5	符合标准要求。	
42	GX-B1310/21-3-26408	2026. 7. 5	符合标准要求。	


43	GX-B1310/21-3-26418	2026. 7. 5	符合标准要求。		 2026.05.05
44	GX-B1310/21-3-26409	2026. 7. 5	符合标准要求。		 2026.05.05

45	GX-B1310/21-3-26404	2026. 7. 5	符合标准要求。	FOOTPRINTS <i>City</i> CITY STORIES  2026/04/25 16:11
46	GX-B1310/21-3-26401	2026. 7. 5	符合标准要求。	 2026.04.22

47	GX-B1310/21-3-26411	2026. 7. 5	符合标准要求。		
48	GX-B1310/21-3-26415	2026. 7. 5	符合标准要求。		

49	GX-B1310/21-3-26407	2026. 7. 5	符合标准要求。		
50	GX-B1310/21-3-26417	2026. 7. 5	符合标准要求。		

51	GX-B1310/21-3-26413	2026. 7. 5	符合标准要求。		
52	GX-B1310/21-3-26412	2026. 7. 5	符合标准要求。		

53	GX-B1310/21-3-26416	2026. 7. 5	符合标准要求。	
54	GX-B1310/21-3-26403	2026. 7. 5	符合标准要求。	

55	GX-B1310/21-3-26400	2026. 7. 5	符合标准要求。		
56	GX-B1310/21-3-26410	2026. 7. 5	符合标准要求。		

57	GX-B1310/21-3-26414	2026. 7. 5	符合标准要求。	 2026.04.24
58	GX-B1309/26-3-26022	2026. 7. 5	所检项目合格。	 2026.05.04

59	GX-B1500/26-3-26102	2026. 7. 5	综合判定：合格。	
60	GX-B1500/26-3-26103	2026. 7. 5	综合判定：合格。	

61	GX-B1500/26-3-26104	2026. 7. 5	综合判定：合格。	
62	GX-B1304/26-3-26014	2026年7月2日	综合判定：合格。	

63	GX-B1304/26-3-26013	2026年7月2日	综合判定：合格。	
----	---------------------	-----------	----------	---